

Kingston Plantation Master Association, Inc.

Inspected: May 28, 2025 • Revised on: September 15, 2025
Myrtle Beach, SC

RESERVE STUDY

Kingston Plantation



Kingston Plantation Master Association, Inc.
Myrtle Beach, South Carolina

Dear Board of Directors of Kingston Plantation Master Association, Inc.:

At the direction of the Board that recognizes the need for proper reserve planning, we have conducted a *Reserve Study* of Kingston Plantation Master Association, Inc. in Myrtle Beach, South Carolina and submit our findings in this report. The effective date of this study is the date of our visual, noninvasive inspection, May 28, 2025.

This *Reserve Study* exceeds the Association of Professional Reserve Analysts (APRA) standards fulfilling the requirements of a “Level II Reserve Study Update.”

An ongoing review by the Board and an Update of this Reserve Study are necessary to ensure an equitable funding plan since a Reserve Study is a snapshot in time. We recommend the Board budget for an Update to this Reserve Study in two- to three-years. We look forward to continuing to help Kingston Plantation Master Association, Inc. plan for a successful future.

As part of our long-term thinking and everyday commitment to our clients, we are available to answer any questions you may have regarding this study.

Respectfully submitted on September 15, 2025 by

Reserve Advisors, LLC

Visual Inspection and Report by: J.J. Barron
Review by: Kevin Hayes, Regional Engineering Manager
Alan M. Ebert, RS¹, PRA², Director of Quality Assurance



¹ RS (Reserve Specialist) is the reserve provider professional designation of the Community Associations Institute (CAI) representing America's more than 300,000 condominium, cooperative and homeowners associations.

² PRA (Professional Reserve Analyst) is the professional designation of the Association of Professional Reserve Analysts. Learn more about APRA at <http://www.apra-usa.com>.



NEW TO RESERVE STUDIES?



**ACCESS OUR
QUICK START GUIDE**



Table of Contents

1. RESERVE STUDY EXECUTIVE SUMMARY	1.1
2. RESERVE STUDY REPORT	2.1
3. RESERVE EXPENDITURES and FUNDING PLAN.....	3.1
4. RESERVE COMPONENT DETAIL.....	4.1
Laurel Court Meeting House Exterior Building Elements	4.1
Awning.....	4.1
Fences, Trash Enclosure, Wood	4.2
Pergolas, Wood	4.3
Roofs Assemblies, Asphalt Shingles	4.4
Walls, Stucco.....	4.7
Windows and Doors	4.10
Laurel Court Meeting Building Interior Elements.....	4.12
Air Handling Units, Split Systems	4.12
Floor Coverings, Carpet, Hallways	4.14
Furnishings	4.15
Light Fixtures	4.15
Rest Rooms.....	4.16
Room Divider, Acoustical	4.17
Wall Coverings	4.18
Property Site Elements	4.19
Asphalt Pavement	4.19
Boardwalks, Wood.....	4.23
Boardwalk Beach Access, Wood.....	4.25
Bridge, Concrete, South Hampton to Embassy Suites	4.27
Bridges, Wood	4.28
Concrete Sidewalks.....	4.31
Fences, Aluminum.....	4.32
Fences, Wood, Gloucester	4.33
Fence, Wood, North Perimeter	4.34
Fountain	4.35
Gate Entry System, Barcode Readers.....	4.37
Gate Entry System, Canterbury III.....	4.38



Gate House, Renovations	4.39
Gates, Swing Arms.....	4.40
Gazebo, Richmond Park	4.41
Guardrail, Wood, Plantation Lakes Drive.....	4.42
Irrigation System, Pumps and Controls	4.43
Light Fixtures, Bollard.....	4.43
Light Poles and Fixtures	4.44
Mail Station, Richmond Park	4.45
Mail Station, West Hyde Park.....	4.46
Maintenance Building	4.47
Pavers, Masonry.....	4.49
Pond, Aerators.....	4.50
Ponds, Bulkhead, Timber	4.51
Security System.....	4.52
Signage, Monuments, Sub-Associations	4.53
Signage, Street and Traffic.....	4.55
Pool Elements.....	4.57
Concrete Deck.....	4.57
Cover, Vinyl.....	4.59
Fence, Wood	4.59
Furniture	4.61
Mechanical Equipment	4.62
Light Poles and Fixtures	4.64
Rest Rooms.....	4.64
Pool House, Roof, Asphalt Shingles, St. James.....	4.66
Pool House, Roofs, Thermoplastic, Beach Pool.....	4.69
Pool House, Walls, EIFS, Beach Pool	4.70
Pool House, Walls, Siding, Fiber Cement, St. James.....	4.73
Pool Finishes, Plaster and Tile	4.75
Structures and Decks	4.76
Reserve Study Update.....	4.77
5. METHODOLOGY	5.1
6. CREDENTIALS	6.1



7. DEFINITIONS7.1

8. PROFESSIONAL SERVICE CONDITIONS8.1



1. RESERVE STUDY EXECUTIVE SUMMARY

Client: Kingston Plantation Master Association, Inc. (Kingston Plantation)

Location: Myrtle Beach, South Carolina

Reference: 171942

Property Basics: Kingston Plantation Master Association, Inc. is a master association which is responsible for the common elements shared by 1,386 units. The community was built in 1985. The community contains a meeting building, two pool houses and two pools.

Reserve Components Identified: 85 Reserve Components.

Inspection Date: May 28, 2025. We conducted previous inspections in 2018, 2020 and 2022.

Funding Goal: The Funding Goal of this Reserve Study is to maintain reserves above an adequate, not excessive threshold during one or more years of significant expenditures. Our recommended Funding Plan recognizes this threshold funding year in 2055 due to the repaving of the asphalt pavement.

Methodology: We use the Cash Flow Method to compute the Reserve Funding Plan. This method offsets future variable Reserve Expenditures with existing and future stable levels of reserve funding. Our application of this method also considers:

- Current and future local costs of replacement
- 2.25% anticipated annual rate of return on invested reserves
- 3.3% future Inflation Rate for estimating Future Replacement Costs

Sources for Local Costs of Replacement: Our proprietary database, historical costs and published sources, i.e., R.S. Means, Incorporated.

Unaudited Cash Status of Reserve Fund:

- \$2,657,282 as of April 30, 2025
- 2025 budgeted Reserve Contributions of \$435,000

Project Prioritization: We note anticipated Reserve Expenditures for the next 30 years in the **Reserve Expenditures** tables and include a **Five-Year Outlook** table following the **Reserve Funding Plan** in Section 3. We recommend the Association prioritize the following projects in the next five years based on the conditions identified:

- Stucco paint finish applications and partial replacements to limit water infiltration into the Laurel Court Meeting building, and to maintain a uniformly clean appearance of the building
- Systematic coordinated replacements and repairs to the boardwalks
- Systematic coordinated replacements and repairs to the bridges
- Concrete sidewalk partial replacements due to noted deterioration


Recommended Reserve Funding: We recommend the following in order to achieve a stable and equitable Cash Flow Methodology Funding Plan:

- We recommend the Association adopt a reserve budget of \$339,700 in 2026
- Inflationary increases thereafter through 2055, the limit of this study's Cash Flow Analysis
- 2026 Reserve Contribution of \$339,700 is equivalent to an average monthly contribution of \$20.42 per owner.



Kingston Plantation Recommended Reserve Funding Table and Graph

Year	Reserve Contributions (\$)	Reserve Balances (\$)	Year	Reserve Contributions (\$)	Reserve Balances (\$)	Year	Reserve Contributions (\$)	Reserve Balances (\$)
2026	339,700	2,120,048	2036	470,100	1,764,570	2046	650,400	4,270,027
2027	350,900	1,999,362	2037	485,600	1,939,830	2047	671,900	3,538,611
2028	362,500	1,646,496	2038	501,600	2,262,626	2048	694,100	3,936,184
2029	374,500	1,544,149	2039	518,200	1,737,488	2049	717,000	3,218,163
2030	386,900	1,675,701	2040	535,300	2,004,802	2050	740,700	3,336,693
2031	399,700	1,240,194	2041	553,000	2,275,274	2051	765,100	3,743,788
2032	412,900	1,315,925	2042	571,200	2,780,496	2052	790,300	2,879,497
2033	426,500	970,531	2043	590,000	3,071,032	2053	816,400	2,360,038
2034	440,600	1,325,378	2044	609,500	3,605,643	2054	843,300	1,944,654
2035	455,100	1,462,139	2045	629,600	3,855,472	2055	871,100	372,310





2. RESERVE STUDY REPORT

At the direction of the Board that recognizes the need for proper reserve planning, we have conducted a *Reserve Study* of

Kingston Plantation Master Association, Inc.

Myrtle Beach, South Carolina

and submit our findings in this report. The effective date of this study is the date of our visual, noninvasive inspection, May 28, 2025. We conducted previous inspections in 2018, 2020 and 2022.

We present our findings and recommendations in the following report sections and spreadsheets:

- **Identification of Property** - Segregates all property into several areas of responsibility for repair or replacement
- **Reserve Expenditures** - Identifies reserve components and related quantities, useful lives, remaining useful lives and future reserve expenditures during the next 30 years
- **Reserve Funding Plan** - Presents the recommended Reserve Contributions and year-end Reserve Balances for the next 30 years
- **Five-Year Outlook** - Identifies reserve components and anticipated reserve expenditures during the first five years
- **Reserve Component Detail** - Describes the reserve components, includes photographic documentation of the condition of various property elements, describes our recommendations for repairs or replacement, and includes detailed solutions and procedures for replacements for the benefit of current and future board members
- **Methodology** - Lists the national standards, methods and procedures used to develop the Reserve Study
- **Definitions** - Contains definitions of terms used in the Reserve Study, consistent with national standards
- **Professional Service Conditions** - Describes Assumptions and Professional Service Conditions
- **Credentials and Resources**

IDENTIFICATION OF PROPERTY



Our investigation includes Reserve Components or property elements as set forth in your Declaration or which were identified as part of your request for proposed services. The Expenditure tables in Section 3 list the elements contained in this study. Our analysis begins by segregating the property elements into several areas of responsibility for repair and replacement.

Our process of identification helps assure that future boards and the management team understand whether reserves, the operating budget or Owners fund certain replacements and assists in preparation of the annual budget. We derive these segregated classes of property from our review of the information provided by the Association and through conversations with Management. These classes of property include:

- Reserve Components
- Long-Lived Property Elements
- Operating Budget Funded Repairs and Replacements
- Property Maintained by Owners

We advise the Board conduct an annual review of these classes of property to confirm its policy concerning the manner of funding, i.e., from reserves or the operating budget. Reserve Components are defined by CAI as property elements with:

- Kingston Plantation responsibility
- Limited useful life expectancies
- Predictable remaining useful life expectancies
- Replacement cost above a minimum threshold

The following tables depict the items excluded from the Reserve Expenditure plan:

Excluded Components

for
Kingston Plantation
Master Association, Inc.
Myrtle Beach, South Carolina

Operating Budget Components

Repairs normally funded through the Operating Budget and Expenditures less than \$6,000 (These relatively minor expenditures have a limited effect on the recommended Reserve Contributions.)

The operating budget provides money for the repair and replacement of certain Reserve Components. The Association may develop independent criteria for use of operating and reserve funds.

- Bus Shelters¹
- Doors, Metal, Laurel Court Meeting Building, Interim Replacements
- Fences, Wood, Gloucester on the Point, Paint Finish Applications
- Fences, Wood, Split-Rail
- Flagpoles
- Irrigation System²
- Landscape
- Light Fixtures, Exterior, Laurel Court Meeting Building and Pool Houses
- Mail Stations, Interim Paint Finish Applications and Repairs
- Paint Finishes, Touch-Up
- Pipes, Interior Building, Domestic Water, Sanitary Waste and Vent, Meeting House
- Pump Houses, Exterior Renovations
- Pumps Less Than Five-HP (Horsepower)
- Signage, Street, Traffic and Miscellaneous
- Valves³
- Water Heaters, Common

¹ Management informs us that there is no longer a bus route through the property and the shelters are no longer in use.

² Per Management

³ We assume replacement as needed in lieu of an aggregate replacement of all valves as a single event.

Excluded Components

for
Kingston Plantation
Master Association, Inc.
Myrtle Beach, South Carolina

Long-Lived Components		
These elements may not have predictable Remaining Useful Lives or their replacement may occur beyond the scope of this study. The operating budget should fund infrequent repairs. Funding untimely or unexpected replacements from reserves will necessitate increases to Reserve Contributions. Periodic updates of this Reserve Study will help determine the merits of adjusting the Reserve Funding Plan.	Useful Life	Estimated Cost
• Electrical Systems, Common	to 70+	N/A
• Foundations, Gate House, Meeting House and Pump Houses	Indeterminate	N/A
• Pipes, Interior Building, Domestic Water, Sanitary Waste and Vent, Gate House (2017)	to 80	N/A
• Pipes, Subsurface Utilities	to 85+	N/A
• Structural Frames, Gate House, Meeting House and Pump Houses	Indeterminate	N/A
• Walls, Fiber Cement Siding, Gate House (2017)	to 50	N/A
• Windows and Doors, Gate House (2017)	to 40	N/A

Others Responsibility Components
Certain items have been designated as the responsibility of Others to repair or replace.
• Asphalt Pavement, Parking Areas at Embassy Suites, Conference Center and Splash Park ¹
• Asphalt Pavement, Queensway Boulevard from Wetherby Way to Plantation Lakes Drive ¹
• Fence, Wood, South Perimeter ¹
• Gate Elements, South Entrance ¹
• Intercom Panel ¹
• Lift Station ²
• Light Poles and Fixtures with Serial Numbers ³
• Parking Garages, Margate ⁴
• Ponds, Maintenance and Sediment Removal ¹
• Pump House #5 ¹
• Residence Buildings and Townhomes ⁴
• The Landing Sport and Health Center and Associated Elements (Including Sports Courts)
• Vehicles, Maintenance Carts ⁵
¹ Developer ² Municipality ³ Santee Cooper ⁴ Separate Associations ⁵ Leased

3. RESERVE EXPENDITURES and FUNDING PLAN

The tables following this introduction present:

Reserve Expenditures

- Line item numbers
- Total quantities
- Quantities replaced per phase (in a single year)
- Reserve component inventory
- Estimated first year of event (i.e., replacement, application, etc.)
- Life analysis showing
 - useful life
 - remaining useful life
- 2025 local cost of replacement
 - Per unit
 - Per phase
 - Replacement of total quantity
- Percentage of future expenditures anticipated during the next 30 years
- Schedule of estimated future costs for each reserve component including inflation

Reserve Funding Plan

- Reserves at the beginning of each year
- Total recommended reserve contributions
- Estimated interest earned from invested reserves
- Anticipated expenditures by year
- Anticipated reserves at year end

Five-Year Outlook

- Line item numbers
- Reserve component inventory of only the expenditures anticipated to occur within the first five years
- Schedule of estimated future costs for each reserve component anticipated to occur within the first five years

The purpose of a Reserve Study is to provide an opinion of reasonable annual Reserve Contributions. Prediction of exact timing and costs of minor Reserve Expenditures typically will not significantly affect the 30-year cash flow analysis. Adjustments to the times and/or costs of expenditures may not always result in an adjustment in the recommended Reserve Contributions.

Financial statements prepared by your association, by you or others might rely in part on information contained in this section. For your convenience, we have provided an electronic data file containing the tables of ***Reserve Expenditures*** and ***Reserve Funding Plan***.

RESERVE EXPENDITURES

**Kingston Plantation
Master Association, Inc.**
Myrtle Beach, South Carolina

Explanatory Notes:

- 1) **3.3%** is the estimated Inflation Rate for estimating Future Replacement Costs.
- 2) **FY2025** is Fiscal Year beginning January 1, 2025 and ending December 31, 2025.

Line Item	Total Quantity	Per Phase Quantity	Units	Reserve Component Inventory	Estimated 1st Year of Event	Life Analysis		Costs, \$			Percentage of Future Expenditures	RUL = 0 FY2025	1 2026	2 2027	3 2028	4 2029	5 2030	6 2031	7 2032	8 2033	9 2034	10 2035	11 2036	12 2037	13 2038	14 2039	15 2040	
						Useful Years	Remaining	Unit (2025)	Per Phase (2025)	Total (2025)																		
Laurel Court Meeting Building Exterior Elements																												
1.015	1	1	Allowance	Awning, Canvas (2025 is Planned)	2025	5 to 10	0	7,200.00	7,200	7,200	0.2%	7,200																
1.020	1	1	Allowance	Awning, Canvas and Frame (Includes Light Fixtures)	2035	to 30	10	17,600.00	17,600	17,600	0.1%											24,351						
1.151	1	1	Allowance	Fences, Trash Enclosure, Wood (Incl. Concrete Flatwork Partial Replacements)	2040	15 to 20	15	6,000.00	6,000	6,000	0.0%																9,765	
1.261	1	1	Each	Pergola, Wood, Front Elevation	2028	25 to 30	3	14,300.00	14,300	14,300	0.1%				15,763													
1.280	48	48	Squares	Roof Assemblies, Asphalt Shingles	2033	15 to 20	8	500.00	24,000	24,000	0.4%									31,118								
1.880	2,300	2,300	Square Feet	Walls, Stucco and Trim, Paint Finishes (2025 is Planned)	2025	6 to 8	0	2.30	5,290	5,290	0.3%	5,290						6,428							7,810			
1.980	560	560	Square Feet	Windows and Doors, Wood Frames	2048	to 40	23	74.00	41,440	41,440	0.4%																	
Laurel Court Meeting Building Interior Elements																												
2.061	1	1	Each	Air Handling Unit, Heating and Cooling Unit, Carrier, 7.5-ton, 2017	2035	15 to 20	10	12,500.00	12,500	12,500	0.2%																17,295	
2.062	1	1	Each	Air Handling Unit, Heating and Cooling Unit, ICP, 7.5-ton, 2014	2032	15 to 20	7	12,500.00	12,500	12,500	0.2%								15,690									
2.071	1	1	Each	Air Handling and Condensing Units, Split System, 4-ton	2038	15 to 20	13	7,200.00	7,200	7,200	0.1%																10,981	
2.200	280	280	Square Yards	Floor Coverings, Carpet (Includes Paint Finishes and Vinyl Tile)	2026	8 to 12	1	80.00	22,400	22,400	0.5%		23,139														32,015	
2.450	1	1	Allowance	Furnishings	2026	to 10	1	13,600.00	13,600	13,600	0.3%		14,049														19,438	
2.560	1	1	Allowance	Light Fixtures	2046	to 30	21	15,000.00	15,000	15,000	0.1%																	
2.900	2	2	Each	Rest Rooms, Renovation	2028	to 20	3	14,000.00	28,000	28,000	0.4%				30,864													
2.921	260	260	Square Feet	Room Divider, Acoustical	2026	to 35	1	100.00	26,000	26,000	0.1%		26,858															
2.980	2,350	2,350	Square Feet	Wall Coverings	2036	to 20	11	7.00	16,450	16,450	0.1%																23,511	
Property Site Elements																												
4.020	89,980	35,992	Square Yards	Asphalt Pavement, Crack Repair, Patch, and Striping, Partial (2025 is Planned)	2025	3 to 5	0 to 30+	1.25	44,990	112,475	2.5%	30,000					52,920										62,247	73,219
4.040	3	1	Allowance	Asphalt Pavement, Mill and Overlay, Partial	2031	to 25	6 to 22	500,000.00	500,000	1,500,000	17.7%							607,536										787,725
4.051	9,000	1,286	Square Feet	Boardwalks, Wood, Boardwalk Replacement, Phased (2025 is Planned)	2025	to 35	0 to 30	55.00	70,714	495,000	3.7%	5,000					83,178										97,838	115,083
4.053	550	550	Square Feet	Boardwalk Beach Access, Wood, Brighton, Boardwalk Replacement	2027	to 35	2	60.00	33,000	33,000	0.2%			35,214														
4.055	340	340	Square Feet	Boardwalk Beach Access, Wood, Embassy Suites North, Boardwalk Replacement (2025 is Planned)	2025	to 35	0	68.00	23,120	23,120	0.1%	23,120																
4.057	625	625	Square Feet	Boardwalk Beach Access, Wood, Embassy Suites South, Boardwalk Replacement, Partial (2025 is Planned)	2025	to 35	0	68.00	42,500	42,500	0.2%	42,857																
4.059	675	675	Square Feet	Boardwalk Beach Access, Wood, Margate, Boardwalk Replacement	2027	to 35	2	60.00	40,500	40,500	0.2%			43,217														
4.061	700	350	Square Feet	Boardwalk Beach Access, Wood, North Hampton, Boardwalk Replacement, Phased (2025 and 2026 is Planned)	2025	to 35	0 to 1	68.00	23,800	47,600	0.3%	24,792	30,000															
4.063	275	138	Square Feet	Boardwalk Beach Access, Wood, South Hampton, Boardwalk Replacement, Phased (2025 and 2026 is Planned)	2025	to 35	0 to 1	68.00	9,350	18,700	0.1%	14,873	15,000															
4.068	1	1	Allowance	Bridge, Concrete, South Hampton to Embassy Suites, Inspections and Capital Repairs	2034	10 to 15	9	60,000.00	60,000	60,000	1.0%																80,363	
4.071	530	530	Square Feet	Bridge, Wood, Laurel Court East, Complete Replacement (2025 is Planned)	2025	to 35	0	68.00	36,040	36,040	0.9%	180,000																
4.073	2,500	357	Square Feet	Bridge, Wood, Laurel Court West, Complete Replacement, Phased	2026	to 35	1 to 31	78.00	27,857	195,000	1.3%		28,776					33,848									39,814	
4.075	1,250	179	Square Feet	Bridge, Wood, North Hampton, Complete Replacement, Phased	2032	to 35	7 to 37	80.00	14,286	100,000	0.6%								17,931								21,091	
4.077	1,725	246	Square Feet	Bridges, Wood, Plantation Lakes Drive, Complete Replacement, Phased (2025 is Planned)	2026	to 35	1 to 31	116.00	28,586	200,100	2.1%		200,000					34,734									40,856	
4.079	850	121	Square Feet	Bridges, Wood, Sidewalks, Complete Replacement, Phased	2026	to 35	1 to 31	86.00	10,443	73,100	0.5%		10,788					12,689									14,925	
4.081	560	80	Square Feet	Bridge, Wood, St. James Park, Complete Replacement, Phased	2033	to 35	8 to 38	90.00	7,200	50,400	0.3%								9,335								10,981	
4.083	275	275	Square Feet	Bridge, Wood, West Hyde Park Mailbox Station, Complete Replacement, Phased	2028	to 35	3	55.00	15,125	15,125	0.1%				16,672													
4.140	125,600	1,215	Square Feet	Concrete Sidewalks, Partial	2025	to 65	0 to 30+	19.00	23,094	2,386,400	5.7%	23,094	23,856	24,643	25,457	26,297	27,165	28,061	28,987	29,944	30,932	31,952	33,007	34,096	35,221	36,384	37,584	
4.200	100	100	Linear Feet	Fence, Aluminum, Margate	2048	to 30	23	57.00	5,700	5,700	0.1%																	
4.201	855	855	Linear Feet	Fence, Aluminum, West Perimeter, 2013	2043	to 30	18	57.00	48,735	48,735	0.4%																	
4.202	1,000	1,000	Linear Feet	Fence, Aluminum, West Perimeter, 2019	2049	to 30	24	57.00	57,000	57,000	0.6%																	
4.285	400	400	Linear Feet	Fences, Wood, Gloucester	2040	to 30	15	99.00	39,600	39,600	0.3%																64,447	
4.286	2,470	2,470	Linear Feet	Fence, Wood, North Perimeter	2037	to 15	12	33.00	81,510	81,510	1.5%																120,341	
4.291	2,625	2,625	Square Feet	Fountain, Finish Applications and Concrete Repairs	2033	8 to 12	8	38.00	99,750	99,750	1.5%										129,335							
4.310	2	2	Each	Gate Entry System, Barcode Readers	2033	to 5	8	9,500.00	19,000	19,000	0.8%																28,977	
4.311	1	1	Allowance	Gate Entry System, Canterbury III	2033	to 15	8	6,000.00	6,000	6,000	0.1%																7,780	

RESERVE EXPENDITURES

**Kingston Plantation
Master Association, Inc.
Myrtle Beach, South Carolina**

Line Item	Total Quantity	Per Phase Quantity	Units	Reserve Component Inventory	Estimated 1st Year of Event	Life Analysis		Costs, \$			Percentage of Future Expenditures	16 2041	17 2042	18 2043	19 2044	20 2045	21 2046	22 2047	23 2048	24 2049	25 2050	26 2051	27 2052	28 2053	29 2054	30 2055					
						Useful Years	Remaining	Unit (2025)	Per Phase (2025)	Total (2025)																					
Laurel Court Meeting Building Exterior Elements																															
1.015	1	1	Allowance	Awning, Canvas (2025 is Planned)	2025	5 to 10	0	7,200.00	7,200	7,200	0.2%	12,104														15,694					
1.020	1	1	Allowance	Awning, Canvas and Frame (Includes Light Fixtures)	2035	to 30	10	17,600.00	17,600	17,600	0.1%																				
1.151	1	1	Allowance	Fences, Trash Enclosure, Wood (Incl. Concrete Flatwork Partial Replacements)	2040	15 to 20	15	6,000.00	6,000	6,000	0.0%																				
1.261	1	1	Each	Pergola, Wood, Front Elevation	2028	25 to 30	3	14,300.00	14,300	14,300	0.1%																				
1.280	48	48	Squares	Roof Assemblies, Asphalt Shingles	2033	15 to 20	8	500.00	24,000	24,000	0.4%															57,666					
1.880	2,300	2,300	Square Feet	Walls, Stucco and Trim, Paint Finishes (2025 is Planned)	2025	6 to 8	0	2.30	5,290	5,290	0.3%			9,490												11,531		14,011			
1.980	560	560	Square Feet	Windows and Doors, Wood Frames	2048	to 40	23	74.00	41,440	41,440	0.4%															87,443					
Laurel Court Meeting Building Interior Elements																															
2.061	1	1	Each	Air Handling Unit, Heating and Cooling Unit, Carrier, 7.5-ton, 2017	2035	15 to 20	10	12,500.00	12,500	12,500	0.2%																	31,026			
2.062	1	1	Each	Air Handling Unit, Heating and Cooling Unit, ICP, 7.5-ton, 2014	2032	15 to 20	7	12,500.00	12,500	12,500	0.2%																	28,146			
2.071	1	1	Each	Air Handling and Condensing Units, Split System, 4-ton	2038	15 to 20	13	7,200.00	7,200	7,200	0.1%																				
2.200	280	280	Square Yards	Floor Coverings, Carpet (Includes Paint Finishes and Vinyl Tile)	2026	8 to 12	1	80.00	22,400	22,400	0.5%																	44,295			
2.450	1	1	Allowance	Furnishings	2026	to 10	1	13,600.00	13,600	13,600	0.3%																	26,893			
2.560	1	1	Allowance	Light Fixtures	2046	to 30	21	15,000.00	15,000	15,000	0.1%																	29,662			
2.900	2	2	Each	Rest Rooms, Renovation	2028	to 20	3	14,000.00	28,000	28,000	0.4%																	59,083			
2.921	260	260	Square Feet	Room Divider, Acoustical	2026	to 35	1	100.00	26,000	26,000	0.1%																				
2.980	2,350	2,350	Square Feet	Wall Coverings	2036	to 20	11	7.00	16,450	16,450	0.1%																				
Property Site Elements																															
4.020	89,980	35,992	Square Yards	Asphalt Pavement, Crack Repair, Patch, and Striping, Partial (2025 is Planned)	2025	3 to 5	0 to 30+	1.25	44,990	112,475	2.5%																	86,124	101,303	119,159	
4.040	3	1	Allowance	Asphalt Pavement, Mill and Overlay, Partial	2031	to 25	6 to 22	500,000.00	500,000	1,500,000	17.7%																		1,021,356	1,324,279	
4.051	9,000	1,286	Square Feet	Boardwalks, Wood, Boardwalk Replacement, Phased (2025 is Planned)	2025	to 35	0 to 30	55.00	70,714	495,000	3.7%																		135,367	159,226	187,290
4.053	550	550	Square Feet	Boardwalk Beach Access, Wood, Brighton, Boardwalk Replacement	2027	to 35	2	60.00	33,000	33,000	0.2%																				
4.055	340	340	Square Feet	Boardwalk Beach Access, Wood, Embassy Suites North, Boardwalk Replacement (2025 is Planned)	2025	to 35	0	68.00	23,120	23,120	0.1%																				
4.057	625	625	Square Feet	Boardwalk Beach Access, Wood, Embassy Suites South, Boardwalk Replacement, Partial (2025 is Planned)	2025	to 35	0	68.00	42,500	42,500	0.2%																				
4.059	675	675	Square Feet	Boardwalk Beach Access, Wood, Margate, Boardwalk Replacement	2027	to 35	2	60.00	40,500	40,500	0.2%																				
4.061	700	350	Square Feet	Boardwalk Beach Access, Wood, North Hampton, Boardwalk Replacement, Phased (2025 and 2026 is Planned)	2025	to 35	0 to 1	68.00	23,800	47,600	0.3%																				
4.063	275	138	Square Feet	Boardwalk Beach Access, Wood, South Hampton, Boardwalk Replacement, Phased (2025 and 2026 is Planned)	2025	to 35	0 to 1	68.00	9,350	18,700	0.1%																				
4.068	1	1	Allowance	Bridge, Concrete, South Hampton to Embassy Suites, Inspections and Capital Repairs	2034	10 to 15	9	60,000.00	60,000	60,000	1.0%																		130,785		
4.071	530	530	Square Feet	Bridge, Wood, Laurel Court East, Complete Replacement (2025 is Planned)	2025	to 35	0	68.00	36,040	36,040	0.9%																				
4.073	2,500	357	Square Feet	Bridge, Wood, Laurel Court West, Complete Replacement, Phased	2026	to 35	1 to 31	78.00	27,857	195,000	1.3%	46,832																	55,086	64,795	
4.075	1,250	179	Square Feet	Bridge, Wood, North Hampton, Complete Replacement, Phased	2032	to 35	7 to 37	80.00	14,286	100,000	0.6%			24,809															29,181	34,325	
4.077	1,725	246	Square Feet	Bridges, Wood, Plantation Lakes Drive, Complete Replacement, Phased (2025 is Planned)	2026	to 35	1 to 31	116.00	28,586	200,100	2.1%	48,057																	56,527	66,491	
4.079	850	121	Square Feet	Bridges, Wood, Sidewalks, Complete Replacement, Phased	2026	to 35	1 to 31	86.00	10,443	73,100	0.5%	17,556																	20,651	24,290	
4.081	560	80	Square Feet	Bridge, Wood, St. James Park, Complete Replacement, Phased	2033	to 35	8 to 38	90.00	7,200	50,400	0.3%			12,916															15,193	17,871	
4.083	275	275	Square Feet	Bridge, Wood, West Hyde Park Mailbox Station, Complete Replacement, Phased	2028	to 35	3	55.00	15,125	15,125	0.1%																				
4.140	125,600	1,215	Square Feet	Concrete Sidewalks, Partial	2025	to 65	0 to 30+	19.00	23,094	2,386,400	5.7%	38,825	40,106	41,429	42,796	44,209	45,668	47,175	48,731	50,340	52,001	53,717	55,489	57,321	59,212	61,166					
4.200	100	100	Linear Feet	Fence, Aluminum, Margate	2048	to 30	23	57.00	5,700	5,700	0.1%																		12,028		
4.201	855	855	Linear Feet	Fence, Aluminum, West Perimeter, 2013	2043	to 30	18	57.00	48,735	48,735	0.4%																		87,427		
4.202	1,000	1,000	Linear Feet	Fence, Aluminum, West Perimeter, 2019	2049	to 30	24	57.00	57,000	57,000	0.6%																		124,246		
4.285	400	400	Linear Feet	Fences, Wood, Gloucester	2040	to 30	15	99.00	39,600	39,600	0.3%																				
4.286	2,470	2,470	Linear Feet	Fence, Wood, North Perimeter	2037	to 15	12	33.00	81,510	81,510	1.5%																		195,848		
4.291	2,625	2,625	Square Feet	Fountain, Finish Applications and Concrete Repairs	2033	8 to 12	8	38.00	99,750	99,750	1.5%																		190,950		
4.310	2	2	Each	Gate Entry System, Barcode Readers	2033	to 5	8	9,500.00	19,000	19,000	0.8%																		34,085	40,092	47,159
4.311	1	1	Allowance	Gate Entry System, Canterbury III	2033	to 15	8	6,000.00	6,000	6,000	0.1%																		12,661		

RESERVE EXPENDITURES

**Kingston Plantation
Master Association, Inc.
Myrtle Beach, South Carolina**

Explanatory Notes:

- 1) **3.3%** is the estimated Inflation Rate for estimating Future Replacement Costs.
- 2) **FY2025** is Fiscal Year beginning January 1, 2025 and ending December 31, 2025.

Line Item	Total Quantity	Per Phase Quantity	Units	Reserve Component Inventory	Estimated 1st Year of Event	Life Analysis		Costs, \$			Percentage of Future Expenditures	RUL = 0 FY2025	1 2026	2 2027	3 2028	4 2029	5 2030	6 2031	7 2032	8 2033	9 2034	10 2035	11 2036	12 2037	13 2038	14 2039	15 2040
						Useful Years	Remaining	Unit (2025)	Per Phase (2025)	Total (2025)																	
4.315	1	1	Allowance	Gate House, Complete Renovation	2047	to 30	22	33,000.00	33,000	33,000	0.3%																
4.316	1	1	Allowance	Gate House, Partial Renovation	2027	to 10	2	8,000.00	8,000	8,000	0.2%		8,537											11,811			
4.320	6	6	Each	Gate Operators, Swing-Arms (2025 is Planned)	2025	to 7	0	4,000.00	24,000	24,000	0.9%	24,000							30,124							37,811	
4.360	1	1	Each	Gazebo, Richmond Park, Renovations (2025 is Planned)	2025	to 25	0	12,500.00	12,500	12,500	0.2%	12,500															
4.371	230	230	Linear Feet	Guardrail, Wood, Plantation Lakes Drive	2030	to 30	5	38.00	8,740	8,740	0.0%					10,280											
4.410	6	1	Allowance	Irrigation System, Pumps and Controls, Phased	2026	to 20	1 to 16	50,000.00	50,000	300,000	3.9%	51,650				56,934			62,758			69,179			76,256		
4.500	4	1	Allowance	Landscape, Partial Replacements, Phased	2026	N/A	1 to 4	200,000.00	200,000	800,000	4.1%	206,600	213,418	220,461	227,736												
4.510	4	1	Allowance	Landscape, Tree Replacement, Phased	2030	N/A	5 to 8	100,000.00	100,000	400,000	2.3%					117,626	121,507	125,517	129,659								
4.541	700	140	Each	Light Fixtures, Bollards, Phased (2025 is Planned)	2025	to 25	0 to 4	525.00	73,500	367,500	6.0%	55,000	75,000	85,000	89,121	92,062											
4.560	75	75	Each	Light Poles and Fixtures (2025 is Planned)	2025	to 30	0	3,800.00	285,000	285,000	3.9%	75,000															
4.600	13	13	Each	Mail Station, Richmond Park, Mailbox Stations	2027	to 25	2	2,300.00	29,900	29,900	0.5%		31,906														
4.601	24	24	Each	Mail Station, West Hyde Park, Mailbox Stations	2028	to 25	3	3,300.00	79,200	79,200	1.3%				87,302												
4.605	1	1	Allowance	Mail Station, Richmond Park, Renovation	2039	15 to 20	14	11,000.00	11,000	11,000	0.1%															17,330	
4.606	1	1	Allowance	Mail Station, West Hyde Park, Renovation	2039	15 to 20	14	13,000.00	13,000	13,000	0.1%															20,481	
4.611	1	1	Allowance	Maintenance Building, Partial Renovation	2032	to 20	7	27,000.00	27,000	27,000	0.5%								33,890								
4.620	1,760	1,760	Square Feet	Pavers, Masonry	2037	15 to 20	12	20.00	35,200	35,200	0.2%													51,969			
4.700	16	4	Each	Ponds, Aerators, Bubblers , Phased	2027	to 10	2 to 8	4,700.00	18,800	75,200	1.8%		20,061		21,407		22,843		24,376				27,756		29,618		
4.710	11,800	11,800	Square Feet	Ponds, Bulkheads, Timber, Capital Repairs	2033	10 to 15	8	20.00	236,000	236,000	1.4%								305,995								
4.711	11,800	5,900	Square Feet	Ponds, Bulkheads, Timber, Replacement, Phased	2052	to 35	27 to 29	70.00	413,000	826,000	9.7%																
4.761	1	1	Allowance	Security System, Surveillance System	2027	to 10	2	11,500.00	11,500	11,500	0.2%		12,272											16,979			
4.800	1	1	Allowance	Signage, Monuments, Sub-Associations	2028	to 25	3	190,000.00	190,000	190,000	3.2%				209,438												
4.810	4	1	Allowance	Signage, Street and Traffic, Phased	2027	15 to 20	2 to 17	33,000.00	33,000	132,000	1.6%		35,214						41,421					48,721			
Beach Pool Elements																											
6.200	5,200	5,200	Square Feet	Concrete Deck, Textured Coating, Partial Replacements and Repairs	2033	8 to 12	8	6.00	31,200	31,200	0.5%								40,454								
6.500	1	1	Allowance	Furniture	2028	to 5	3	16,500.00	16,500	16,500	0.8%				18,188				21,394						25,164		
6.600	5	1	Allowance	Mechanical Equipment, Both Pools (Includes Fountain Equipment), Phased	2026	to 15	1 to 13	7,400.00	7,400	37,000	0.6%	7,644			8,426			9,288			10,238			11,286			
6.601	1	1	Each	Mechanical Equipment, Enclosure	2026	to 25	1	5,500.00	5,500	5,500	0.1%	5,682															
6.751	2	2	Each	Pool House, Rest Rooms, Renovation (Includes Doors)	2039	to 20	14	10,400.00	20,800	20,800	0.2%															32,769	
6.761	775	775	Square Feet	Pool House, Roofs, Thermoplastic	2028	15 to 20	3	20.00	15,500	15,500	0.2%				17,086												
6.771	4,600	4,600	Square Feet	Pool House, Walls, EIFS, Paint Finishes and Capital Repairs (Includes Stand-Alone Walls)	2029	6 to 8	4	5.00	23,000	23,000	0.9%					26,190						31,822					
6.800	1,600	1,600	Square Feet	Pool Finish, Plaster	2029	8 to 12	4	18.00	28,800	28,800	0.4%					32,794										45,373	
6.801	165	165	Square Feet	Pool Finish, Tile	2039	15 to 25	14	40.00	6,600	6,600	0.0%															10,398	
6.900	1,600	1,600	Square Feet	Structure and Deck, Total Replacement	2049	to 60	24	197.00	315,200	315,200	3.2%																
St. James Pool Elements																											
7.200	2,650	2,650	Square Feet	Concrete Deck, Textured Coating, Partial Replacements and Repairs	2033	8 to 12	8	6.00	15,900	15,900	0.2%								20,616								
7.300	1,770	1,770	Square Feet	Cover, Vinyl	2027	to 10	2	4.20	7,434	7,434	0.2%		7,933											10,976			
7.400	230	230	Linear Feet	Fence, Wood	2049	20 to 25	24	49.00	11,270	11,270	0.1%																
7.500	1	1	Allowance	Furniture	2028	to 5	3	17,500.00	17,500	17,500	0.9%				19,290				22,690						26,690		
7.561	4	4	Each	Light Poles and Fixtures (2025 is Planned)	2025	to 25	0	3,500.00	14,000	14,000	0.2%	14,000															
7.751	2	2	Each	Pool House, Rest Rooms, Renovation (Includes Doors)	2039	to 20	14	10,000.00	20,000	20,000	0.1%															31,509	
7.761	9	9	Squares	Pool House, Roof, Asphalt Shingles	2040	15 to 20	15	650.00	5,850	5,850	0.0%															9,521	
7.770	1,600	1,600	Square Feet	Pool House, Walls, Siding, Fiber Cement, Paint Finishes	2035	8 to 10	10	2.00	3,200	3,200	0.1%											4,427					
7.800	1,000	1,000	Square Feet	Pool Finish, Plaster	2029	8 to 12	4	18.00	18,000	18,000	0.2%					20,496										28,358	
7.801	160	160	Square Feet	Pool Finish, Tile	2039	15 to 25	14	40.00	6,400	6,400	0.0%															10,083	
7.900	1,000	1,000	Square Feet	Structure and Deck, Total Replacement	2049	to 60	24	197.00	197,000	197,000	2.0%																

RESERVE EXPENDITURES

**Kingston Plantation
Master Association, Inc.
Myrtle Beach, South Carolina**

Explanatory Notes:

- 1) **3.3%** is the estimated Inflation Rate for estimating Future Replacement Costs.
- 2) **FY2025** is Fiscal Year beginning January 1, 2025 and ending December 31, 2025.

Line Item	Total Quantity	Per Phase Quantity	Units	Reserve Component Inventory	Estimated 1st Year of Event	Life Analysis		Costs, \$			Percentage of Future Expenditures	RUL = 0 FY2025	1 2026	2 2027	3 2028	4 2029	5 2030	6 2031	7 2032	8 2033	9 2034	10 2035	11 2036	12 2037	13 2038	14 2039	15 2040	
						Useful	Remaining	Unit (2025)	Per Phase (2025)	Total (2025)																		
	1	1 Allowance		Reserve Study Update with Site Visit	2028	to 2	3	5,700.00	5,700	5,700	0.0%				6,283													
Anticipated Expenditures, By Year (\$21,171,644 over 30 years)												536,726	719,042	517,414	755,925	512,342	291,168	867,646	365,605	797,330	111,294	349,351	203,566	351,551	225,556	1,087,839	309,617	

RESERVE EXPENDITURES

**Kingston Plantation
Master Association, Inc.
Myrtle Beach, South Carolina**

Line Item	Total Quantity	Per Phase Quantity	Units	Reserve Component Inventory	Estimated 1st Year of Event	Life Analysis		Costs, \$			Percentage of Future Expenditures	16 2041	17 2042	18 2043	19 2044	20 2045	21 2046	22 2047	23 2048	24 2049	25 2050	26 2051	27 2052	28 2053	29 2054	30 2055
						Useful Years	Remaining	Unit (2025)	Per Phase (2025)	Total (2025)																
1	1	1	Allowance	Reserve Study Update with Site Visit	2028	to 2	3	5,700.00	5,700	5,700	0.0%															
Anticipated Expenditures, By Year (\$21,171,644 over 30 years)												330,143	122,223	364,561	149,166	462,775	326,240	1,490,186	379,683	1,514,612	695,092	436,775	1,728,274	1,394,148	1,306,573	2,469,220

RESERVE FUNDING PLAN

CASH FLOW ANALYSIS

Kingston Plantation

Master Association, Inc.

Myrtle Beach, South Carolina

Individual Reserve Budgets & Cash Flows for the Next 30 Years

		FY2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Reserves at Beginning of Year	(Note 1)	2,657,282	2,448,565	2,120,048	1,999,362	1,646,496	1,544,149	1,675,701	1,240,194	1,315,925	970,531	1,325,378	1,462,139	1,764,570	1,939,830	2,262,626	1,737,488
Total Recommended Reserve Contributions	(Note 2)	290,000	339,700	350,900	362,500	374,500	386,900	399,700	412,900	426,500	440,600	455,100	470,100	485,600	501,600	518,200	535,300
Estimated Interest Earned, During Year	(Note 3)	38,009	50,825	45,828	40,560	35,495	35,820	32,439	28,436	25,436	25,542	31,011	35,897	41,211	46,752	44,501	41,632
Anticipated Expenditures, By Year		(536,726)	(719,042)	(517,414)	(755,925)	(512,342)	(291,168)	(867,646)	(365,605)	(797,330)	(111,294)	(349,351)	(203,566)	(351,551)	(225,556)	(1,087,839)	(309,617)
Anticipated Reserves at Year End		\$2,448,565	\$2,120,048	\$1,999,362	\$1,646,496	\$1,544,149	\$1,675,701	\$1,240,194	\$1,315,925	\$970,531	\$1,325,378	\$1,462,139	\$1,764,570	\$1,939,830	\$2,262,626	\$1,737,488	\$2,004,802

(continued)

Individual Reserve Budgets & Cash Flows for the Next 30 Years, Continued

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055
Reserves at Beginning of Year	2,004,802	2,275,274	2,780,496	3,071,032	3,605,643	3,855,472	4,270,027	3,538,611	3,936,184	3,218,163	3,336,693	3,743,788	2,879,497	2,360,038	1,944,654
Total Recommended Reserve Contributions	553,000	571,200	590,000	609,500	629,600	650,400	671,900	694,100	717,000	740,700	765,100	790,300	816,400	843,300	871,100
Estimated Interest Earned, During Year	47,615	56,245	65,097	74,277	83,004	90,395	86,870	83,156	79,591	72,922	78,769	73,683	58,289	47,889	25,776
Anticipated Expenditures, By Year	(330,143)	(122,223)	(364,561)	(149,166)	(462,775)	(326,240)	(1,490,186)	(379,683)	(1,514,612)	(695,092)	(436,775)	(1,728,274)	(1,394,148)	(1,306,573)	(2,469,220)
Anticipated Reserves at Year End	\$2,275,274	\$2,780,496	\$3,071,032	\$3,605,643	\$3,855,472	\$4,270,027	\$3,538,611	\$3,936,184	\$3,218,163	\$3,336,693	\$3,743,788	\$2,879,497	\$2,360,038	\$1,944,654	\$372,310

(NOTES 4&5)

Explanatory Notes:

- 1) Year 2025 starting reserves are as of April 30, 2025; FY2025 starts January 1, 2025 and ends December 31, 2025.
- 2) Reserve Contributions for 2025 are the remaining budgeted 8 months; 2026 is the first year of recommended contributions.
- 3) 2.3% is the estimated annual rate of return on invested reserves; 2025 is a partial year of interest earned.
- 4) Accumulated year 2055 ending reserves consider the need to fund for subsequent replacement of the pond timber bulkheads shortly after 2055, and the age, size, overall condition and complexity of the property.
- 5) Threshold Funding Year (reserve balance at critical point).

FIVE-YEAR OUTLOOK

Kingston Plantation Master Association, Inc. Myrtle Beach, South Carolina

Line Item	Reserve Component Inventory	RUL = 0 FY2025	1 2026	2 2027	3 2028	4 2029	5 2030
Laurel Court Meeting Building Exterior Elements							
1.015	Awning, Canvas (2025 is Planned)	7,200					
1.261	Pergola, Wood, Front Elevation				15,763		
1.880	Walls, Stucco and Trim, Paint Finishes (2025 is Planned)	5,290					
Laurel Court Meeting Building Interior Elements							
2.200	Floor Coverings, Carpet (Includes Paint Finishes and Vinyl Tile)		23,139				
2.450	Furnishings		14,049				
2.900	Rest Rooms, Renovation				30,864		
2.921	Room Divider, Acoustical		26,858				
Property Site Elements							
4.020	Asphalt Pavement, Crack Repair, Patch, and Striping, Partial (2025 is Planned)	30,000					52,920
4.051	Boardwalks, Wood, Boardwalk Replacement, Phased (2025 is Planned)	5,000					83,178
4.053	Boardwalk Beach Access, Wood, Brighton, Boardwalk Replacement			35,214			
4.055	Boardwalk Beach Access, Wood, Embassy Suites North, Boardwalk Replacement (2025 is Planned)	23,120					
4.057	Boardwalk Beach Access, Wood, Embassy Suites South, Boardwalk Replacement, Partial (2025 is Planned)	42,857					
4.059	Boardwalk Beach Access, Wood, Margate, Boardwalk Replacement			43,217			
4.061	Boardwalk Beach Access, Wood, North Hampton, Boardwalk Replacement, Phased (2025 and 2026 is Planned)	24,792	30,000				
4.063	Boardwalk Beach Access, Wood, South Hampton, Boardwalk Replacement, Phased (2025 and 2026 is Planned)	14,873	15,000				
4.071	Bridge, Wood, Laurel Court East, Complete Replacement (2025 is Planned)	180,000					
4.073	Bridge, Wood, Laurel Court West, Complete Replacement, Phased		28,776				
4.077	Bridges, Wood, Plantation Lakes Drive, Complete Replacement, Phased (2025 is Planned)		200,000				
4.079	Bridges, Wood, Sidewalks, Complete Replacement, Phased		10,788				
4.083	Bridge, Wood, West Hyde Park Mailbox Station, Complete Replacement, Phased				16,672		
4.140	Concrete Sidewalks, Partial	23,094	23,856	24,643	25,457	26,297	27,165
4.316	Gate House, Partial Renovation			8,537			
4.320	Gate Operators, Swing-Arms (2025 is Planned)	24,000					
4.360	Gazebo, Richmond Park, Renovations (2025 is Planned)	12,500					
4.371	Guardrail, Wood, Plantation Lakes Drive						10,280
4.410	Irrigation System, Pumps and Controls, Phased		51,650			56,934	
4.500	Landscape, Partial Replacements, Phased		206,600	213,418	220,461	227,736	
4.510	Landscape, Tree Replacement, Phased						117,626
4.541	Light Fixtures, Bollards, Phased (2025 is Planned)	55,000	75,000	85,000	89,121	92,062	
4.560	Light Poles and Fixtures (2025 is Planned)	75,000					
4.600	Mail Station, Richmond Park, Mailbox Stations			31,906			
4.601	Mail Station, West Hyde Park, Mailbox Stations				87,302		
4.700	Ponds, Aerators, Bubblers, Phased			20,061		21,407	
4.761	Security System, Surveillance System			12,272			
4.800	Signage, Monuments, Sub-Associations				209,438		
4.810	Signage, Street and Traffic, Phased			35,214			
Beach Pool Elements							
6.500	Furniture					18,188	

FIVE-YEAR OUTLOOK

**Kingston Plantation
Master Association, Inc.**
Myrtle Beach, South Carolina

Line Item	Reserve Component Inventory	RUL = 0 FY2025	1 2026	2 2027	3 2028	4 2029	5 2030
6.600	Mechanical Equipment, Both Pools (Includes Fountain Equipment), Phased		7,644			8,426	
6.601	Mechanical Equipment, Enclosure		5,682				
6.761	Pool House, Roofs, Thermoplastic				17,086		
6.771	Pool House, Walls, EIFS, Paint Finishes and Capital Repairs (Includes Stand-Alone Walls)					26,190	
6.800	Pool Finish, Plaster					32,794	
St. James Pool Elements							
7.300	Cover, Vinyl			7,933			
7.500	Furniture				19,290		
7.561	Light Poles and Fixtures (2025 is Planned)	14,000					
7.800	Pool Finish, Plaster					20,496	
	Reserve Study Update with Site Visit				6,283		
Anticipated Expenditures, By Year (\$3,332,618 over 5 years)		536,726	719,042	517,414	755,925	512,342	291,168

4. RESERVE COMPONENT DETAIL

The Reserve Component Detail of this *Reserve Study* includes enhanced solutions and procedures for select significant components. This section describes the Reserve Components, documents specific problems and condition assessments, and may include detailed solutions and procedures for necessary capital repairs and replacements for the benefit of current and future board members. We advise the Board use this information to help define the scope and procedures for repair or replacement when soliciting bids or proposals from contractors. *However, the Report in whole or part is not and should not be used as a design specification or design engineering service.*

Laurel Court Meeting House Exterior Building Elements



Meeting house front exterior overview



Meeting house rear exterior overview

Awning

Line Items: 1.015 and 1.020

Quantity: One canvas awning with metal frames

History: The canvas was last replaced in 2017. Management informs us of plans to replace the awnings canvas in 2025

Condition: Fair overall with rust evident.



Awning overview



Awning canvas cover

Useful Life: 5- to 10-years for the canvas and up to 30 years for the frame

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimated cost comes from information provided by the Association.

Fences, Trash Enclosure, Wood

Line Item: 1.151

Quantity: Approximately 70 linear feet of privacy wood fences. The enclosure contains approximately 730 square feet of concrete flatwork.

History: Replaced at an unknown time since 2022

Condition: Good overall with no visible deterioration



Wood fence



Wood fence



Wood fence

Useful Life: 15- to 20-years

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair loose sections, finish deterioration and damage
 - Repair leaning sections and clear vegetation from fence areas which could cause damage

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The Association should anticipate periodic partial replacements due to the non-uniform nature of wood deterioration. Along with these partial replacements, the Association should apply periodic paint applications as needed and fund these activities through the operating budget.

Pergolas, Wood

Line Item: 1.261

Quantity: One wood pergola at the front entrance of the building that comprises approximately 420 square feet

History: Unknown at this time.

Condition: Good overall



Pergola



Pergola

Useful Life: Up to 25 years with periodic maintenance

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect for wood deterioration, and loose or missing fasteners
- Every three years:
 - Power wash with algaecide and application of sealer/stain

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We recommend the Association budget for paint applications and repairs through the operating budget.

Roofs Assemblies, Asphalt Shingles

Line Item: 1.280

Quantity: Approximately 48 squares¹

History: Replaced in 2013.

Condition: Good to fair overall with recent repairs evident from our visual inspection from the ground. Management does not report any active leaks.

¹ We quantify the roof area in squares where one square is equal to 100 square feet of surface area.



Roof overview



Roof overview



Roof overview



Previous repair


Useful Life: 15- to 20-years

Component Detail Notes: The existing roof assembly comprises the following:

- Laminate architectural shingles
- Boston style ridge caps
- Rubber seal with plastic base boot flashing at waste pipes
- Metal drip edge
- Enclosed full weaved valleys

The following cross-sectional schematic illustrates a typical asphalt shingle roof system although it may not reflect the actual configuration at Kingston Plantation:

ROOF SCHEMATIC



© Reserve Advisors

Contractors use one of two methods for replacement of sloped roofs, either an overlayment or a tear-off. Overlayment is the application of new shingles over an existing roof. However, there are many disadvantages to overlayment including hidden defects of the underlying roof system, absorption of more heat resulting in accelerated deterioration of the new and old shingles, and an uneven visual appearance. Therefore, we recommend only the tear-off method of replacement. The tear-off method of replacement includes removal of the existing shingles, flashings if required and underlayments.

Preventative Maintenance Notes: We recommend the Association maintain a service and inspection contract with a qualified professional and record all documentation of repairs conducted. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Record any areas of water infiltration, flashing deterioration, damage or loose shingles
 - Implement repairs as needed if issues are reoccurring
 - Trim tree branches that are near or in contact with roof
- As-needed:
 - Ensure proper ventilation and verify vents are clear of debris and not blocked from attic insulation

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Walls, Stucco

Line Item: 1.880

Quantity: Approximately 2,300 square feet of the building exterior

History: The date of the last painting event is unknown at this time. Management informs us of plans to paint in 2025.

Condition: Fair overall with isolated stains and damage evident.



Stucco wall finishes



Stucco wall finishes



Stucco wall finishes



Stucco wall finishes



Stucco trash enclosure wall



Stucco trash enclosure wall with stains



Stucco wall stains




Stucco damage

Useful Life: We recommend inspections, repairs and paint finish applications every six- to eight-years.

Component Detail Notes: The following graphic details the typical components of a stucco wall system on frame construction although it may not reflect the actual configuration at Kingston Plantation:

STUCCO DETAIL



© Reserve Advisors

Correct and complete preparation of the surface before application of the paint finish maximizes the useful life of the paint finish and surface. The contractor should remove all loose, peeled or blistered paint before application of the new paint finish. The contractor should then power wash the surface to remove all dirt and biological growth. Water-soluble cleaners that will not attack Portland cement are acceptable for removing stains.

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimate of cost is based on information provided by Management and anticipates the following in coordination with each paint finish application:

- Complete inspection of the stucco
- Replacement of deteriorated areas of stucco, concrete and wood trim (The exact amount of material in need of replacement will depend on the actual future conditions and desired appearance. We recommend replacement wherever holes, cracks and deterioration impair the ability of the material to prevent water infiltration.)
- Replacement of sealants as needed

Windows and Doors

Line Item: 1.980

Quantity: Approximately 560 square feet of windows and doors

History: Replaced in 2014

Condition: Good to fair overall with no visible deterioration



Meeting House windows and doors



Meeting House windows and doors


Useful Life: Up to 40 years

Component Detail Notes: Construction includes the following:

- Wood frames
- Dual pane glass
- Fixed windows
- Hinged doors

The following schematic depicts the typical components of a window system although it may not reflect the actual configuration at Kingston Plantation:

WINDOW DETAIL



© Reserve Advisors

Properly designed window assemblies anticipate the penetration of some storm water beyond the gaskets. This infiltrated storm water collects in an internal drainage system and drains, or exits, the frames through weep holes. These weep holes can become clogged with dirt or if a sealant is applied, resulting in trapped storm water. However, as window frames, gaskets and sealants deteriorate, leaks into the interior can result. The windows will eventually need replacement or major capital repairs to prevent water infiltration and damage from wind driven rain.

The thermal efficiencies of the window assemblies are affected by their design and construction components. These components include glazings, thickness of air space between glazings, low-conductivity gas, tinted coatings, low-e coatings and thermal barriers. The Association should thoroughly investigate these component options at the time of replacement. Some manufacturers may include these components as part of the standard product and other manufacturers may consider these components as options for an additional cost. Kingston Plantation should review the specifications provided by the manufacturers to understand the thermal design and construction components of the proposed assemblies.

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair loose weather stripping and/or lock damage
 - Inspect for broken glass and damaged screens
 - Record instances of water infiltration, trapped moisture or leaks

- As-needed:
 - Verify weep holes are unobstructed and not blocked with dirt or sealant, if applicable
 - Replace damaged or deteriorated sliding glass rollers, if applicable

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Laurel Court Meeting Building Interior Elements

Air Handling Units, Split Systems

Line Items: 2.061, 2.062, and 2.071

Quantity: One 7.5-ton *Carrier* system, one 7.5-ton *International Comfort Productions* air handling units, and one 4-ton *Tempstat* split system unit

History: The Association replaced the *Carrier* unit in 2017, the *International Comfort Productions* in 2014, and the *Tempstat* split system unit in 2020

Condition: Reported satisfactory without operational deficiencies



Heating and cooling units



Heating and cooling units



Split system condensing unit

Useful Life: 15- to 20-years

Component Detail Notes: The systems have cooling capacities of 7.5-tons and 4-tons. The split systems use R-410A refrigerant.

Preventative Maintenance Notes: We recommend the Association obtain and adhere to the manufacturer's recommended maintenance plan. We also recommend the Association maintain a maintenance contract with a qualified professional. The required preventative maintenance may vary in frequency and scope based on the unit's age, operational condition, or changes in technology. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Semi-annually:
 - Lubricate motors and bearings
 - Change or clean air filters as needed
 - Inspect condenser base and piping insulation
 - Inspect base pan, coil, cabinet and clear obstructions as necessary
- Annually:
 - Clean coils and drain pans, clean fan assembly, check refrigerant charge, inspect fan drive system and controls
 - Inspect and clean accessible ductwork as needed
 - Clean debris from inside cabinet, inspect condenser compressor and associated tubing for damage

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Floor Coverings, Carpet, Hallways

Line Item: 2.200

Quantity: Approximately 280 square yards at the hallways (Contractor measurements will vary from the actual floor area due to standard roll lengths, patterns and installation waste.)

History: Replaced in 2016.

Condition: Good to fair overall with no significant deterioration evident.



Carpet floor coverings



Carpet floor coverings



Carpet floor coverings

Useful Life: 8- to 12-years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Furnishings

Line Item: 2.450

Quantity: Furnishings and components in the Meeting House include but are not limited to the following elements:

- Folding chairs
- Folding tables
- Pictures/decorations
- Plants
- Television

History: Varies in age. Replacements last conducted in 2016

Condition: Good to fair overall



Furnishings

Useful Life: Varies significantly up to 10 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Due to varied uses, ages and useful lives, we recommend the Association budget \$12,300 plus inflation for phased replacements of up to one hundred percent (100%) of the furnishings per event.

Light Fixtures

Line Item: 2.560

Quantity: Approximately 80 interior wall and ceiling mounted light fixtures

History: Replaced in 2016

Condition: Reported satisfactory overall



Meeting House ceiling fixtures

Useful Life: Up to 30 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Rest Rooms

Line Item: 2.900

Quantity: The rest room components include:

- Tile floor coverings
- Paint finishes
- Light fixtures
- Plumbing fixtures
- Countertops
- Rest room partitions
- Drinking fountains

History: Partially renovated in 2020

Condition: Good to fair overall



Meeting House rest room



Meeting House rest room



Meeting House rest room



Meeting House rest room

Useful Life: Renovation up to every 20 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Room Divider, Acoustical

Line Item: 2.921

Quantity: Approximately 260 square feet

History: Assumed original

Condition: Fair overall



Room Divider

Useful Life: Up to 35 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Wall Coverings

Line Item: 2.980

Quantity: Approximately 2,350 square feet of wall coverings

History: Replaced in 2016.

Condition: Good to fair overall



Lobby finishes



Wall coverings and fixtures

Useful Life: Up to 20 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Property Site Elements

Asphalt Pavement

Line Items: 4.020 and 4.040

Quantity: Approximately 89,980 square yards of asphalt pavement throughout the community

History:

- Repaving: The streets were last overlaid from 2010 to 2013. Various sections were overlaid in 2023
- Repairs: Seal coating was last applied in 2019

Condition: Good overall with no significant deterioration evident



Pavement overview at Plantation Lakes Drive



Pavement overview at Gloucester Terrace Circle



Laurel oaks overview with cracks



Windmere By the Sea overview



Trailer parking area overview



Pavement cracks at trailer parking area



Pavement cracks at Gloucester Terrace Circle



Pavement cracks and previous repairs at Gloucester Terrace Circle



Queensway Boulevard



Pavement overview Cumberland terrace



Pavement overview Cumberland terrace



Pavement cracks at Cumberland terrace



Pavement overview Appledore circle




Pavement cracks Appledore

Useful Life: Up to 25 years with the benefit of crack, patch repairs, sealcoating and striping events every three- to five-years. At the request of Management, we use a five-year useful life for partial crack, patch repairs, sealcoating and striping events and an eight-year useful life for partial mill and overlayments.

Component Detail Notes: Patch repairs are conducted at areas exhibiting settlement, potholes, or excessive cracking. These conditions typically occur near high traffic areas, catch basins, and pavement edges.

The initial installation of asphalt uses at least two lifts, or two separate applications of asphalt, over the base course. The first lift is the binder course. The second lift is the wearing course. The wearing course comprises a finer aggregate for a smoother, more watertight finish. The following diagram depicts the typical components although it may not reflect the actual configuration at Kingston Plantation:



The manner of repaving is either a mill and overlay or total replacement. A mill and overlay is a method of repaving where cracked, worn and failed pavement is mechanically removed or milled until sound pavement is found. A new layer of asphalt is overlaid atop the remaining base course of pavement. Total replacement includes the removal of all existing asphalt down to the base course of aggregate and native soil followed by the application of two or more new lifts of asphalt. We recommend mill and overlay on asphalt pavement that exhibits normal deterioration and wear. We recommend total replacement of asphalt pavement that exhibits severe deterioration, inadequate drainage, pavement that has been overlaid multiple times in the past or where the configuration makes overlayment not possible. Based on the apparent visual condition and configuration of the asphalt pavement, we recommend the mill and overlay method of repaving at Kingston Plantation.

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:

- Inspect for settlement, large cracks and trip hazards, and ensure proper drainage
- Repair areas which could cause vehicular damage such as potholes
- As needed:
 - Perform crack repairs and patching

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The Association plans to conduct partial asphalt patching, seal coating, and striping every five years and performs partial mill and overlayment every eight years.

Boardwalks, Wood

Line Item: 4.051

Quantity: Wood boardwalks at the southeast section of the property which comprise a total of approximately 9,000 square feet, including approximately 2,450 linear feet of wood railings and approximately 65 light fixtures.

History: The Association replaced the decking at sections of the boardwalks and conducted repairs as needed in 2022. The Association has replaced the light fixtures at the railings in 2022 as well. The top railing in various sections were replaced at an unknown time since 2022. Management informs us of plans to do repairs in 2025

Condition: Good to fair overall condition. We note deteriorated and weathered wood deck boards and recent replacements.



Boardwalk overview



Boardwalk overview



Boardwalk overview



Boardwalk overview



Boardwalk overview with previous repairs



Boardwalk overview



Boardwalk overview with previous repairs

Useful Life: Up to 35 years with the benefit of interim replacement of the decking and structure repairs. Management informs us the Association conducts annual repairs and partial replacements using in-house labor and funds this aggressive maintenance through the operating budget.

Component Detail Notes: Boardwalk construction includes the following:

- Toe-nailed connections (Nails driven at an angle into the weakest part of the wood result in an increased potential for failed connections)
- Deck boards fastened with screws and nails. Nail fasteners have a tendency to pull out as the wood warps.
- Wood railings with vertical pickets
- Wood column supported frames
- Wood frames fastened with bolts

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect to identify and correct any unsafe conditions
 - Secure loose fasteners and replace deteriorated fasteners
 - Replace deteriorated wood components
 - Check railing stability and fasteners
- Every three years:
 - Power wash with algaecide and application of sealer/stain if applicable

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimate of cost and timing is based on information provided by Management and the Board.

Boardwalk Beach Access, Wood

Line Items: 4.053 through 4.063

Quantity: Six wood boardwalk beach accesses that provide access to the beach from the boardwalks. The locations and quantities are listed in the following table:

Location	Square Feet	Linear Feet of Railing
Brighton	550	195
Embassy Suites North	340	95
Embassy Suites South	625	265
Margate	675	225
North Hampton	700	215
South Hampton	275	90

History: The Association has replaced the decking and railings at sections of the beach accesses and conducted repairs as needed at an unknown date. Management informs us of various near term replacements

Condition: Fair overall condition. We note deteriorated and weathered wood deck boards, exposed and rusted nails.



Beach Access



Beach Access



Beach Access

Useful Life: Up to 35 years with the benefit of interim replacement of the decking and structure repairs. Management informs us the Association conducts annual repairs and partial replacements using in-house labor and funds this aggressive maintenance through the operating budget.

Component Detail Notes: Boardwalk construction includes the following:

- Toe-nailed connections (Nails driven at an angle into the weakest part of the wood result in an increased potential for failed connections)
- Deck boards fastened with screws and nails. Nail fasteners have a tendency to pull out as the wood warps.
- Wood railings with vertical pickets
- Wood column supported frames
- Wood frames fastened with bolts

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect to identify and correct any unsafe conditions
 - Secure loose fasteners and replace deteriorated fasteners
 - Replace deteriorated wood components
 - Check railing stability and fasteners
- Every three years:
 - Power wash with algaecide and application of sealer/stain if applicable

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimate of cost and timing is based on information provided by Management and the Board.

Bridge, Concrete, South Hampton to Embassy Suites

Line Item: 4.068

Quantity: One concrete pedestrian bridge that connects the South Hampton building to the Embassy Suites building.

History: Major renovation completed in 2017

Condition: Good to fair overall with deteriorated finishes, control joint sealant deterioration, rust spots and textured coating delamination evident



Pedestrian bridge overview



Sealant deterioration at control joint



Rust spots evidence



Finish deterioration



Bridge overview



Bridge coating deterioration

Useful Life: 10- to 15-years for capital repairs including a close-up visual inspection, patching of delaminated concrete, and routing and filling of cracked concrete

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimated cost and timing comes from information provided by Management. At the request of Management, we include for partial replacements at each event.

Bridges, Wood

Line Items: 4.071 through 4.083

Quantity/History: The Association maintains multiple wood bridges located throughout the property. The locations, quantities and year of replacement are listed in the following table:

Location	Square Feet	Linear Feet of Railing	Age
Laurel Court East	530	135	2021
Laurel Court West	2,500	500	Original
North Hampton	1,250	175	2021
Plantation Lakes Drive	1,725	575	2018
Sidewalks	850	170	Original
St. James Park	560	140	Original
West Hyde Park Mailbox Station	275	60	2020

Condition: Ranges from Good to fair. We note deteriorated and weathered wood deck boards, exposed and rusted nails.



West Hyde park bridge



Sidewalk bridge



Bridge at Plantation Lakes Drive



Saint James Park bridge



East Laurel Court bridge



Laurel Court west bridge

Useful Life: Up to 35 years with the benefit of interim replacement of the decking and structure repairs. Management informs us the Association conducts annual repairs and partial replacements using in-house labor and funds this aggressive maintenance through the operating budget.

Component Detail Notes: Bridge construction includes the following:

- Toe-nailed connections (Nails driven at an angle into the weakest part of the wood result in an increased potential for failed connections)
- Deck boards fastened with screws and nails. Nail fasteners have a tendency to pull out as the wood warps.
- Wood railings with vertical pickets and horizontal pickets (at Laurel Court East). Horizontal pickets promote climbing and are potentially dangerous.
- Wood column supported frames
- Wood frames fastened with bolts

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect to identify and correct any unsafe conditions
 - Secure loose fasteners and replace deteriorated fasteners
 - Replace deteriorated wood components
 - Check railing stability and fasteners
- Every three years:
 - Power wash with algaecide and application of sealer/stain if applicable

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimate of cost and timing is based on information provided by Management and the Board.

Concrete Sidewalks

Line Item: 4.140

Quantity: Approximately 125,600 square feet

Condition: Fair overall with cracks, trip hazards and settlement evident.



Concrete sidewalk



Concrete sidewalk



Sidewalk cracks and settlement



Sidewalk cracks

Useful Life: Up to 65 years although interim deterioration of areas is common

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair major cracks, spalls and trip hazards
 - Mark with orange safety paint prior to replacement or repair
 - Repair or perform concrete leveling in areas in immediate need of repair or possible safety hazard

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We estimate that up to 36,464 square feet of concrete sidewalks, or thirty percent (30%) of the total, will require replacement during the next 30 years. Our cost estimate and timing for replacement is based on information provided to us by the Association.

Fences, Aluminum

Line Items: 4.200, 4.201, and 4.202


Quantity: Approximately 100 linear feet at Margate and a total of 1,855 linear feet along the West Perimeter

History: The Association installed the fence at the Margate in 2018, and the fences at the west perimeter in 2013 and 2019.

Condition: Good to fair overall



Aluminum fence at Castle Ford Circle



Aluminum fence at Margate



Aluminum fence at Margate



Aluminum fence at Cumberland Terrace

Useful Life: Up to 30 years (The useful life of the finish is indeterminate. Future updates of this Reserve Study will again consider the need to refinish the railings based on condition.)

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair loose fasteners or sections, and damage
 - Repair leaning sections and clear vegetation from fence areas which could cause damage

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Fences, Wood, Gloucester

Line Item: 4.285

Quantity: Approximately 400 linear feet at Gloucester on the Point

History: Repairs conducted as needed

Condition: Fair to poor overall condition with areas of deteriorated wood siding



Wood fence



Finish and wood deterioration

Useful Life: up to 30 years

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair loose sections, finish deterioration and damage
 - Repair leaning sections and clear vegetation from fence areas which could cause damage

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The Association should anticipate periodic partial replacements due to the non-uniform nature of wood deterioration. Along with these partial replacements, the Association should apply periodic paint applications as needed and fund these activities through the operating budget.

Fence, Wood, North Perimeter

Line Item: 4.286

Quantity: 2,470 linear feet

History: Replaced in 2022

Condition: Good to fair overall



North perimeter fence



North perimeter fence



North perimeter fence



North perimeter fence

Useful Life: Up to 15 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The Association should anticipate periodic partial replacements funded through the operating budget due to the non-uniform nature of wood deterioration. Our cost estimate for replacement is based on information provided to us by the Association.

Fountain

Line Item: 4.291

Quantity: Approximately 2,625 square feet

History: Representatives of the Association inform us that the Association applies a paint finish to the fountain on an as-needed basis. The date of the last paint finish is unknown at this time. We recommend the Association install a plaster finish at the fountain.

Condition: Good to fair overall



Fountain overview



Fountain overview



Fountain overview



Fountain overview

Useful Life: 8- to 12-years

Component Detail Notes: Finish replacement provides the opportunity to inspect the fountain structure and to allow for partial repairs of the underlying concrete surfaces as needed. To maintain the integrity of the fountain structure, we recommend the Association budget for the following:

- Removal and replacement of the finish
- Replacement of fountains as needed
- Concrete structure repairs as needed

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our cost estimate for near-term repairs is based on information provided to us by the Association.

Gate Entry System, Barcode Readers

Line Item: 4.310

Quantity: Two barcode readers

History: Installed in 2018

Condition: Reported satisfactory



Gate entry barcode scanner



Gate entry barcode scanner

Useful Life: up to five years

Preventative Maintenance Notes: We recommend the Association obtain and adhere to the manufacturer's recommended maintenance plan. The required preventative maintenance may vary in frequency and scope based on the unit's age, operational condition, or changes in technology. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Monthly:
 - Inspect panel for damage and ensure the panel is mounted securely, tighten or replace any loose or damaged fasteners.
 - Inspect panel for proper operation of buttons, displays, microphone and speaker.
- Annually:
 - Check power connections, and if applicable, functionality of battery power supply systems

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Gate Entry System, Canterbury III

Line Item: 4.311

Quantity: One keypad system at Canterbury III

History: Installed in 2018.

Condition: Reported satisfactory



Canterbury gate entry system

Useful Life: Up to 15 years

Preventative Maintenance Notes: We recommend the Association obtain and adhere to the manufacturer's recommended maintenance plan. The required preventative maintenance may vary in frequency and scope based on the unit's age, operational condition, or changes in technology. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Monthly:
 - Inspect panel for damage and ensure the panel is mounted securely, tighten or replace any loose or damaged fasteners.
 - Inspect panel for proper operation of buttons, displays, microphone and speaker.
- Annually:
 - Check power connections, and if applicable, functionality of battery power supply systems

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Gate House, Renovations

Line Items: 4.315 and 4.316

Quantity: One allowance

History: The gate house was constructed in 2017.

Condition: The gate house elements are in good overall condition.



Gatehouse exterior overview



Gate house metal roof



Gate house exterior light fixtures



Gatehouse exterior overview

Useful Life: Complete renovations every 30 years and partial renovations every 10 years

Component Detail Notes: The gate house includes the following components:

- Standing seam metal roof
- Board and batten fiber cement siding at the exterior walls
- Aluminum gutters and downspouts
- Windows and doors
- Interior and exterior light fixtures
- Paint finishes at the interior walls and ceiling

- Floor coverings at the interior
- Plumbing fixtures
- Countertops
- Furnishings

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The complete renovation should include replacement of all the components listed above.

The partial renovations should include the following:

- Application of paint finish to all surfaces
- Replacement of the interior floor coverings
- Replacement of the furnishings

Gates, Swing Arms

Line Item: 4.320

Quantity: Six swing arm gates

History: Installed in 2018. Management inform us that an unknown quantity of swing arms will be replaced in 2025

Condition: Reported in satisfactory operational conditions



Lift arm operator



Lift arm operator

Useful Life: Up to seven years for the operators

Preventative Maintenance Notes: The status of preventative maintenance was unavailable to us during our inspection. We recommend the Association obtain and adhere to the manufacturer's recommended maintenance plan. We also recommend the Association maintain a maintenance contract with a qualified professional. The required

preventative maintenance may vary in frequency and scope based on the unit's age, operational condition, or changes in technology. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Semi-annually:
 - Ensure gates operate freely
 - Inspect for any wear, rust and loose fasteners
 - Inspect and correct tension in belts and chains, and lubricate hinges and chains as necessary
 - Check alignment of pulleys
 - Check for no oil leakage at the gear box
 - Check the control board for water damage. Clean and remove insects and other pests as needed.
 - Check all wiring for insulation damage and loose connections. If applicable, check functionality of battery power supply systems

Priority/Criticality: Not recommended to defer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimated cost comes from information provided by the Association.

Gazebo, Richmond Park

Line Item: 4.360

Quantity: One wood framed gazebo at Richmond Park with an asphalt shingle roof and mortared pavers

History: Renovated in 2019. Management informs us of plans of various renovations in 2025.

Condition: Good overall



Gazebo overview



Shingle roof

Useful Life: Up to 25 years with periodic maintenance

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We recommend the Association budget for paint applications and repairs through the operating budget. Our estimated cost comes from information provided by the Association.

Guardrail, Wood, Plantation Lakes Drive

Line Item: 4.371

Quantity: Approximately 230 linear feet

History: Unknown

Condition: Good to fair overall



Plantation Lakes Drive guardrail



Plantation Lakes Drive guardrail

Useful Life: Up to 30 years



Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Irrigation System, Pumps and Controls

Line Item: 4.410

Quantity: Six pumps ranging from 7.5-HP to 25-HP with associated control panels, valves and variable frequency drives (VFDs)

History: Components vary in age

Condition: Reported satisfactory without operational deficiencies

Useful Life: Up to 20 years

Preventative Maintenance Notes: The required preventative maintenance may vary in frequency and scope based on the unit's age, operational condition, or changes in technology.

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Light Fixtures, Bollard

Line Item: 4.541

Quantity: 200 bollard light fixtures. At the request of the Association, we include a total of 700 light fixtures due to plans to replace the mushroom light fixtures with bollard light fixtures.

History: Reportedly original. Management informs us of plans to replace various light fixtures in 2025 - 2029

Condition: Fair overall.



Bollard light fixtures

Useful Life: Up to 25 years

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- As-needed:
 - Inspect and repair broken or dislodged fixtures, and leaning or damaged poles
 - Replaced burned out bulbs as needed

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimated cost and timing comes from information provided by the Association

Light Poles and Fixtures

Line Item: 4.560

Quantity: 214 poles with light fixtures

History: Original. Management informs us of plans to replace various light poles and fixtures in 2025.

Condition: Fair overall

Useful Life: Up to 30 years

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- As-needed:
 - Inspect and repair broken or dislodged fixtures, and leaning or damaged poles

- Replaced burned out bulbs as needed

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimated cost and timing comes from information provided by the Association.

Mail Station, Richmond Park

Line Items: 4.600 and 4.605

History: The Association replaced the roof and applied paint finishes in 2019. The light fixtures are assumed to be original. The 13 mailbox stations are original.

Condition: The roof and paint finishes are in good overall condition. The mailbox stations are in fair to poor condition. We note rust formation and deterioration at the undersides of the mailbox stations.



Mailbox stations



Gazebo overview



Gazebo roof



Mailbox station rust

Useful Life: Up to 15- to 20-years for the renovation of the mail stations and up to 25 years for replacement of the mailbox stations

Component Detail Notes: The mail station includes the following:

- Seven squares of asphalt shingle roofs
- Wood structure and trim
- Light fixtures
- Concrete pad

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Complete renovations should include the following:

- Replacement of the asphalt shingle roof assembly
- Paint finishes and structure repairs to the wood structure
- Replacement of the light fixtures
- Partial replacement of the concrete pad

Mail Station, West Hyde Park

Line Items: 4.601 and 4.606

History: The Association replaced the roof and applied paint finishes in 2019. The light fixtures are assumed to be original. The 24 mailbox stations are original.

Condition: The roof and paint finishes are in good overall condition. The mailbox stations are in fair to poor condition. We note finish deterioration and rust at the mailbox stations.



West Hyde Park mailbox kiosk



Mailbox stations



Mailbox station rust and finish deterioration



Mailbox stations

Useful Life: Up to 15- to 20-years for the renovation of the mail stations and up to 25 years for replacement of the mailbox stations

Component Detail Notes: The mail station includes the following:

- Seven squares of asphalt shingle roofs
- 660 square feet of wood siding
- Wood structure and trim
- Light fixtures
- Concrete pad
- Signage

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Complete renovations should include the following:

- Replacement of the asphalt shingle roof assembly
- Paint finishes and structure repairs to the wood structure, including partial replacements of wood siding
- Replacement of the light fixtures
- Replacement of the signage
- Partial replacement of the concrete pad

Maintenance Building

Line Item: 4.611

History: Constructed in 2012

Condition: Fair overall with damaged siding evident



Maintenance building overview



Maintenance building siding overview



Maintenance building overview



Maintenance building roof overview



Damaged siding

Useful Life: Partial renovations every 20 years

Component Detail Notes:

- 2,300 square feet of metal roofing
- 2,750 square feet of aluminum siding

- Garage doors (3)
- Exterior doors (4)
- Tile floor and wall coverings at the rest room and kitchenette
- Paint finishes at the rest room and kitchenette
- Plumbing fixtures at the rest room and kitchenette
- Countertops at the kitchenette

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The *partial* renovations should include the following:

- Replacement of the garage doors
- Replacement of the exterior doors

Pavers, Masonry

Line Item: 4.620

Quantity: Approximately 1,760 square feet at the main entrance to the community and the gate house

History: Installed in 2017

Condition: Good to fair overall with isolated paver spalls evident



Masonry pavers at entrance overview




Paver spalls at entrance

Useful Life: 15- to 20-years

Component Detail Notes: The following diagram depicts the typical components of a masonry paver system although it may not reflect the actual configuration at Kingston Plantation:

MASONRY PAVER DIAGRAM



© Reserve Advisors

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair settlement, trip hazards and paver spalls at heavy traffic areas
 - Re-set and/or reseal damaged pavers as necessary
 - Periodically clean and remove overgrown vegetation as needed

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We suggest the Association conduct interim resetting and replacement of minor areas of pavers as normal maintenance, funded from the operating budget.

Pond, Aerators

Line Item: 4.700

Quantity: Eight bubbler aerators and three fountain aerators

History: Aerators vary in age. Approximately nine years in age

Condition: Reported satisfactory without operational deficiencies



Bubbler aerator

Useful Life: Up to 10 years

Component Detail Notes: The use of small pumps, motors and aerators circulates pond water and increases the amount of entrained oxygen in the water, increasing water quality and reducing algae growths.

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The Association informs us all fountain aerators will be replaced with bubbler aerators going forward.

Ponds, Bulkhead, Timber

Line Items: 4.710 and 4.711

Quantity: Approximately 11,800 square feet at Lake Arrowhead and pumps houses based on information provided to us by the Association

History: Mostly original. Replacements were conducted in 2022

Conditions: Fair overall.



Wood bulkhead



Wood bulkhead



Wood bulkhead

Useful Life: Inspections and capital repairs every 10- to 15-years and complete replacement up to every 35 years

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our cost estimate for replacement is based on information provided to us by the Association. Our cost for repairs includes allowances for a complete inspection and partial replacement of up to twenty percent (20%) of the bulkheads.

Security System

Line Item: 4.761

Quantity: Kingston Plantation utilizes the following security system components including cameras, monitors and recording devices.

History: Varies in age



Condition: Reported satisfactory without operational deficiencies

Useful Life: Up to 10 years

Preventative Maintenance Notes: We recommend the Association obtain and adhere to the manufacturer's recommended maintenance plan. The required preventative maintenance may vary in frequency and scope based on the unit's age, operational condition, or changes in technology. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Monthly:
 - Check cameras for proper focus, fields of view are unobstructed and camera and lenses are clean and dust-free
 - Check recording equipment for proper operation
 - Verify monitors are free from distortion with correct brightness and contrast
- Annually:
 - Check exposed wiring and cables for wear, proper connections and signal transmission
 - Check power connections, and if applicable, functionality of battery power supply systems

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. The Association should anticipate replacement of all of the security system components per event.

Signage, Monuments, Sub-Associations

Line Item: 4.800

Quantity: The property identification signage includes the following elements:

- Light fixtures
- Fences
- Signage
- Masonry
- Stucco
- Stamped concrete
- Landscaping

History: Mostly original with repairs and paint finishes conducted as necessary

Condition: Fair overall. We note isolated cracks evident.



Entrance monument



Entrance monument



Entrance monument



Entrance monument



Entrance monument



Entrance monument



Sign cracks

Useful Life: Up to 25 years

Component Detail Notes: Community signage contributes to the overall aesthetic appearance of the property to owners and potential buyers. Renovation or replacement of community signs is often predicated upon the desire to "update" the perceived identity of the community rather than for utilitarian concerns. Therefore, the specific times for replacement or renovation are discretionary.

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair damage, vandalism and loose components
 - Verify lighting is working properly
 - Touch-up paint finish applications if applicable

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our cost for renovation includes repairs to the masonry and replacement of the remaining components listed above.

Signage, Street and Traffic

Line Item: 4.810

Quantity: Street identification and traffic signs throughout the community

History: Repaired and replaced as necessary

Condition: Fair overall



Traffic management signage



Traffic management signage

Useful Life: 15- to 20-years

Component Detail Notes: The community signs contribute to the overall aesthetic appearance of the property to owners and potential buyers. Replacement of community signs is often predicated upon the desire to "update" the perceived identity of the community rather than for utilitarian concerns. Therefore, the specific time for replacement of the signs is discretionary.

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair damage, vandalism and loose components
 - Verify lighting is working properly if applicable
 - Touch-up paint finish applications if applicable

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Pool Elements



St. James Park Pool overview



Beach Pool overview

Concrete Deck

Line Items: 6.200 and 7.200

Quantity: Approximately 5,200 square feet at the Beach Pool and approximately 2,650 square feet at the St. James Pool

History: Unknown at this time

Condition: Good overall with isolated stains evident



Concrete pool deck overview at St. James Park



Concrete pool deck overview at St. James Park



Concrete pool deck overview at St. James Park



Concrete pool deck overview at the Beach Pool



Concrete pool deck overview at the Beach Pool



Concrete pool deck overview at the Beach Pool

Useful Life: The useful life of a concrete pool deck is up to 60 years or more with timely repairs. We recommend the Association conduct inspections, partial replacements and repairs to the deck every 8- to 12-years in conjunction with coating replacements.

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Semi-annually:
 - Inspect and repair large cracks, trip hazards, and possible safety hazards
 - Inspect and repair pool coping for cracks, settlement, heaves or sealant deterioration
 - Repair concrete spalling and conduct coating repairs in areas with delamination
 - Schedule periodic pressure cleanings as needed

Priority/Criticality: Defer only upon opinion of independent professional or engineer



Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We recommend the Association budget for the following per event:

- Selective cut out and replacements of up to ten percent (10%) of concrete
- Crack repairs as needed
- Mortar joint repairs
- Caulk replacement
- Coating replacement

Cover, Vinyl

Line Item: 7.300

Quantity: Approximately 1,770 square feet for the St. James Pool

History: Unknown

Condition: Reported in good overall condition

Useful Life: Up to 10 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimated cost comes from information provided by the Association

Fence, Wood

Line Item: 7.400

Quantity: Approximately 230 linear feet at St. James Pool

History: Original

Condition: Fair overall condition with isolated dislodged pickets evident



Wood pool fence



Wood pool fence



Dislodged picket

Useful Life: 20- to 25-years

Component Detail Notes: The Association should anticipate periodic partial replacements due to the non-uniform nature of wood deterioration. Along with these partial replacements, the Association should apply periodic paint applications as needed and fund these activities through the operating budget.

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair loose sections, finish deterioration and damage
 - Repair leaning sections and clear vegetation from fence areas which could cause damage

Priority/Criticality: Not recommended to defer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Furniture

Line Items: 6.500 and 7.500

Quantity: The pool furniture at the Beach Pool includes the following:

- Chairs
- Lounges
- Tables
- Ladders and life safety equipment

The pool furniture at the St. James Pool includes the following:

- Chairs
- Lounges
- Tables
- Umbrellas
- Trash receptacles
- Life safety equipment

History: Furniture varies in age

Condition: Good to fair overall



St. James Pool furniture overview



St. James Pool furniture overview



St. James Pool furniture overview



Beach Pool furniture overview



Beach Pool furniture overview

Useful Life: Up to five years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We recommend interim re-strapping, refinishing, cushion replacements, reupholstering and other repairs to the furniture as normal maintenance to maximize its useful life.

Mechanical Equipment

Line Items: 6.600 and 6.601

Quantity: The mechanical equipment includes the following:

- Automatic chlorinator and controls
- Electrical panel and exhaust fans
- Interconnected pipe, fittings and valves
- Pumps, filters, and heaters

History: Varies in age

Condition: Reported satisfactory overall



Pool mechanical equipment



Pool mechanical equipment



Pool mechanical equipment



Pool mechanical equipment enclosure

Useful Life: Up to 15 years and up to 25 years for the enclosure

Preventative Maintenance Notes: We recommend the Association maintain a maintenance contract with a qualified professional and follow the manufacturer’s specific recommended maintenance and local, state and/or federal inspection guidelines.

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the *Reserve Expenditures* table in Section 3. Failure of the pool mechanical equipment as a single event is unlikely. Therefore, we include replacement of up to fifty percent (50%) of the equipment per event. We consider interim replacement of motors and minor repairs as normal maintenance.

Light Poles and Fixtures

Line Item: 7.561

Quantity: Four metal poles with light fixtures

History: The poles are reportedly original. The Association replaced the fixtures in 2019.

Condition: Fair overall.



Laurel Court pool light poles and fixtures

Useful Life: Up to 25 years

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- As-needed:
 - Inspect and repair broken or dislodged fixtures, and leaning or damaged poles
 - Replaced burned out bulbs as needed

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Rest Rooms

Line Items: 6.751 and 7.751

Quantity: The rest room components include:

- Tile floor and wall coverings
- Paint finishes on the walls and ceilings
- Light fixtures

- Plumbing fixtures

History: Renovated in 2019

Condition: Good to fair overall with rust evident at the exhaust fan, toiles, and metal bar



St. James Pool restroom overview



Beach Pool restroom overview



Beach Pool restroom overview



St. James Pool restroom overview



St. James Pool restroom rust



Beach Pool restroom overview



St. James Pool restroom toilet rust



Beach Pool restroom toilet rust



St. James Pool rest room overview



Rust at exhaust fan

Useful Life: Renovation up to every 25 years

Priority/Criticality: Per Board discretion

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Pool House, Roof, Asphalt Shingles, St. James

Line Item: 7.761

Quantity: Approximately nine squares

History: Replaced in 2020

Condition: Good overall with no visible deterioration evident from our visual inspection from the ground. Management do not report a history of leaks.



Roof overview



Roof overview



Roof overview


Useful Life: 15- to 20-years

Component Detail Notes: The existing roof assembly comprises the following:

- Laminate architectural shingles
- Boston style ridge caps
- Rubber seal with plastic base boot flashing at waste pipes
- Metal drip edge
- Enclosed full weaved valleys

The following cross-sectional schematic illustrates a typical asphalt shingle roof system although it may not reflect the actual configuration at Kingston Plantation:

ROOF SCHEMATIC



© Reserve Advisors

Contractors use one of two methods for replacement of sloped roofs, either an overlayment or a tear-off. Overlayment is the application of new shingles over an existing roof. However, there are many disadvantages to overlayment including hidden defects of the underlying roof system, absorption of more heat resulting in accelerated deterioration of the new and old shingles, and an uneven visual appearance. Therefore, we recommend only the tear-off method of replacement. The tear-off method of replacement includes removal of the existing shingles, flashings if required and underlayments.

The Association should plan to coordinate the replacement of gutters and downspouts with the adjacent roofs. This will result in the most economical unit price and minimize the possibility of damage to other roof components as compared to separate replacements.

Preventative Maintenance Notes: We recommend the Association maintain a service and inspection contract with a qualified professional and record all documentation of repairs conducted. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Record any areas of water infiltration, flashing deterioration, damage or loose shingles
 - Implement repairs as needed if issues are reoccurring
 - Trim tree branches that are near or in contact with roof
- As-needed:

- Ensure proper ventilation and verify vents are clear of debris and not blocked from attic insulation

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Pool House, Roofs, Thermoplastic, Beach Pool

Line Item: 6.761

Quantity: Approximately 775 square feet of roofing

History: Unknown

Condition: Reported in good overall

Useful Life: Up to 15- to 20-years

Component Detail Notes: Thermoplastic roofs include the following:

- Polyvinyl chloride (PVC or simply vinyl)
- PVC alloys or compounded thermoplastics
- Thermoplastic olefin (TPO)
- Chlorinated polyethylene (CPE)

The following characteristics define most thermoplastic roofs:

- Attachment to the roof deck is either fully adhered, mechanical or ballasted
- Membranes are commonly white and reinforced with polyester
- Seams are sealed with heat or chemical welding
- Sheet widths range from 6- to 12-feet wide
- Sheets are typically 40- to 100-mils thick
- Single ply (one layer)

Over time, exposure to ultraviolet light, heat and weather degrade the membrane. This degradation results in membrane damage from thermal expansion and contraction, adverse weather and pedestrian traffic. The aging process makes the membrane less pliable and more difficult to maintain. Ponding water on the roof can increase the effects of ultraviolet light on the membrane and contaminants in ponded water can cause the membrane to deteriorate prematurely. Thermoplastic roofs (especially TPO) are relatively new and their long-term performance is not well defined.

Contractors can install a new thermoplastic roof in one of two ways: *tear-off* or an *overlay*. An *overlay* is the application of a new roof membrane over an existing roof. This method, although initially more economical, often covers up problems with the deck, flashing and

saturated insulation. The *tear-off* method of replacement includes removal of the existing roofing, flashings and insulation, and installation of a new roofing system.

The contractor should follow the manufacturer's directions and specifications upon installation of the roof. The contractor should remove the original insulation if saturated or compacted and apply a new layer of insulation per the manufacturer's instructions. The insulation should fit loosely with gaps no greater than ¼ inch. Gaps will cause failure of the membrane later. Mechanical fastening of the insulation is the best manner of installation.

Preventative Maintenance Notes: We recommend the Association maintain a service and inspection contract with a qualified professional and record all documentation of repairs conducted. We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Semi-annually:
 - Note drainage issues with water ponding after 48 hours of rainfall event. Verify scuppers and drains are free of debris. Replace damaged or missing drain covers.
 - Inspect perimeter flashing for loose fasteners, deflections, and sealant damage
 - Verify membrane surface is free of ruptures or damage, and areas of extensive blistering or bubbling
 - Remove oil spills or contaminants from mechanical equipment
 - In areas of possible foot traffic, remove any sharp debris or trash and note areas of crushed insulation
 - If frequency of leaks increase or location of water infiltration is unknown, we recommend the consideration of a thermal image inspection

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the ***Reserve Expenditures*** table in Section 3.

Pool House, Walls, EIFS, Beach Pool

Line Item: 6.771

Quantity: Approximately 4,600 square feet of the building exterior. This quantity includes the adjacent stand-alone walls at the pool area.

History: Paint finishes conducted as needed

Condition: Fair overall with isolated damage evident



EIFS at pool house overview



EIFS at pool house overview



EIFS at pool house overview



EIFS at pool house damage



EIFS at pool house overview




EIFS pool wall overview

Useful Life: EIFS (Exterior Insulation Finish System) wall systems have indefinitely long useful lives with timely repairs and finish applications. We recommend repairs and finish applications every six- to eight-years.

Component Detail Notes: The following graphic details the typical components of an EIFS wall panel although it may not reflect the actual configuration at Kingston Plantation:

EIFS DETAIL



© Reserve Advisors

Correct and complete preparation of the surface before application of the paint finish maximizes the useful life of the paint finish and surface. The environment and normal settlement can cause minor deterioration of the EIFS wall panels. Prior to the application of the new finish coat, the contractor should remove and replace all loose, cracked or deteriorated sections of the EIFS walls. The contractor should then wash the surface to remove all dirt or chalking of the prior paint finish.

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. Our estimate of cost anticipates the following in coordination with each paint finish application:

- Complete inspection of the EIFS
- Crack repairs as needed (Each paint product has the limited ability to cover and seal cracks but we recommend repair of all cracks which exceed the ability of the paint product to bridge.)
- Replacement of one percent (1%) of the EIFS walls (The exact amount of area in need of repair will be discretionary based on the actual future conditions and the desired appearance.)
- Replacement of up to fifty percent (50%) of the sealants in coordination with each paint finish application.


Pool House, Walls, Siding, Fiber Cement, St. James

Line Item: 7.770

Quantity: Approximately 1,600 square feet of the exterior walls. This quantity includes the soffit, fascia and trim.

History: Installed at an unknown time since 2022

Condition: The siding is in good overall condition and the paint finishes are in good overall condition with no visible deterioration evident.



Fiber cement siding



Fiber cement siding



Fiber cement siding



Fiber cement siding

Useful Life: With the benefit of periodic maintenance, applications of this type of material can have a useful life of up to 50 years. This useful life is based on a high-grade pre-finish applied in the factory. This useful life is also dependent upon paint applications and partial replacements up to every 8- to 10-years.


Component Detail Notes: Fiber cement siding is made from a combination of cement, sand and cellulose fiber. Manufacturing of the siding utilizes a steam curing process to increase strength and dimensional stability. The siding is also manufactured in layers

forming a sheet of desired thickness. A wood grain imprint is typically applied to the exposed surface. Fiber cement siding offers many advantages over other types of siding. These advantages include:

- Capable of withstanding salt spray and ultraviolet rays
- Dimensional stability (will not buckle or warp as easily as other materials)
- Paint applications last longer compared to wood siding
- Resistant to insects, birds and fire

The following diagram details a typical fiber cement siding system at the interface with other building components although it may not reflect the actual configuration at Kingston Plantation:

FIBER CEMENT SIDING DETAIL



© Reserve Advisors

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Annually:
 - Inspect and repair damage, loose boards and finish stains
 - Periodic pressure cleaning at areas with organic growth
 - Touch-up paint finish applications as needed and sealing of butt joints and field cut end joints

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Pool Finishes, Plaster and Tile

Line Items: 6.800, 6.801, 7.800, and 7.801

Quantity: Approximately 1,600 square feet of plaster based on the horizontal surface area and approximately 165 linear feet of tile at the beach pool and approximately 1,000 square feet of plaster and approximately 160 linear feet of tile at the St. James Pool.

History:

- Plaster finish: Replaced in 2019 at both pools
- Tile: Replaced in 2019 at both pools

Condition: Good overall



St. James Pool plaster finish with tile perimeter



St. James Pool plaster finish with tile perimeter



Beach Pool plaster finish with tile perimeter

Useful Life: 8- to 12-years for the plaster and 15- to 25-years for the tile

Preventative Maintenance Notes: We note the following select recommended preventative maintenance activities to maximize the remaining useful life:

- Semi-annually:

- Inspect and patch areas of significant plaster delamination, coping damage and structure cracks
- Inspect main drain connection and anti-entrapment covers, pressure test circulation piping and valves
- Test handrails and safety features for proper operation

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3. We recommend the Association budget for full tile replacement every other plaster replacement event. Removal and replacement of the finish provides the opportunity to inspect the pool structure and to allow for partial repairs of the underlying concrete surfaces as needed. To maintain the integrity of the pool structure, we recommend the Association budget for the following:

- Removal and replacement of the plaster finish
- Partial replacements of the scuppers and coping as needed
- Replacement of tiles as needed
- Replacement of joint sealants as needed
- Concrete structure repairs as needed

Structures and Decks

Line Items: 6.900 and 7.900

Quantity: Approximately 1,600 square feet of horizontal surface area at the beach pool and 1,000 square feet at the St. James pool

History: Original

Conditions: Visually appears in good to fair condition. The concrete floors and walls have a plaster finish. This finish makes it difficult to thoroughly inspect the concrete structure during a noninvasive visual inspection.

Useful Life: Up to 60 years

Component Detail Notes: The need to replace a pool structure depends on the condition of the concrete structure, the condition of the embedded or concealed water circulation piping, possible long term uneven settlement of the structure, and the increasing cost of repair and maintenance. Deterioration of any one of these component systems could result in complete replacement of the pool. For example, deferral of a deteriorated piping system could result in settlement and cracks in the pool structure. This mode of failure is more common as the system ages and deterioration of the piping system goes undetected. For reserve budgeting purposes, we recommend Kingston Plantation plan to replace the following components:

- Concrete deck
- Pool structure

- Subsurface piping

Priority/Criticality: Defer only upon opinion of independent professional or engineer

Expenditure Detail Notes: Expenditure timing and costs are depicted in the **Reserve Expenditures** table in Section 3.

Reserve Study Update

An ongoing review by the Board and an Update of this Reserve Study are necessary to ensure an equitable funding plan since a Reserve Study is a snapshot in time. Many variables change after the study is conducted that may result in significant overfunding or underfunding the reserve account. Variables that may affect the Reserve Funding Plan include, but are not limited to:

- Deferred or accelerated capital projects based on Board discretion
- Changes in the interest rates on reserve investments
- Changes in the *local* construction inflation rate
- Additions and deletions to the Reserve Component Inventory
- The presence or absence of maintenance programs
- Unusually mild or extreme weather conditions
- Technological advancements

Periodic updates incorporate these variable changes since the last Reserve Study or Update. We recommend the Board budget for an Update to this Reserve Study every three years. Budgeting for an Update demonstrates the Board's objective to continue fulfilling its fiduciary responsibility to maintain the commonly owned property and to fund reserves appropriately.

5. METHODOLOGY

Reserves for replacement are the amounts of money required for future expenditures to repair or replace Reserve Components that wear out before the entire facility or project wears out. Reserving funds for future repair or replacement of the Reserve Components is also one of the most reliable ways of protecting the value of the property's infrastructure and marketability.

Kingston Plantation can fund capital repairs and replacements in any combination of the following:

1. Increases in the operating budget during years when the shortages occur
2. Loans using borrowed capital for major replacement projects
3. Level monthly reserve assessments annually adjusted upward for inflation to increase reserves to fund the expected major future expenditures
4. Special assessments

We do not advocate special assessments or loans unless near term circumstances dictate otherwise. Although loans provide a gradual method of funding a replacement, the costs are higher than if the Association were to accumulate reserves ahead of the actual replacement. Interest earnings on reserves also accumulate in this process of saving or reserving for future replacements, thereby defraying the amount of gradual reserve collections. We advocate the third method of *Level Monthly Reserve Assessments* with relatively minor annual adjustments. The method ensures that Owners pay their "fair share" of the weathering and aging of the commonly owned property each year. Level reserve assessments preserve the property and enhance the resale value of the homes.

This Reserve Study is in compliance with and exceeds the National standards¹ set forth by the Association of Professional Reserve Analysts (APRA) fulfilling the requirements of a "Level II Reserve Study Update." These standards require a Reserve Component to have a "predictable remaining Useful Life." Estimating Remaining Useful Lives and Reserve Expenditures beyond 30 years is often indeterminate. Long-Lived Property Elements are necessarily excluded from this analysis. We considered the following factors in our analysis:

- The Cash Flow Method to compute, project and illustrate the 30-year Reserve Funding Plan
- Local² costs of material, equipment and labor
- Current and future costs of replacement for the Reserve Components
- Costs of demolition as part of the cost of replacement
- Local economic conditions and a historical perspective to arrive at our estimate of long-term future inflation for construction costs in Myrtle Beach, South Carolina at an annual inflation rate³. Isolated or regional

¹ Identified in the APRA "Standards - Terms and Definitions" and the CAI "Terms and Definitions".

² See Credentials for additional information on our use of published sources of cost data.

³ Derived from Marshall & Swift, historical costs and the Bureau of Labor Statistics.

markets of greater construction (development) activity may experience slightly greater rates of inflation for both construction materials and labor.

- The past and current maintenance practices of Kingston Plantation and their effects on remaining useful lives
- Financial information provided by the Association pertaining to the cash status of the reserve fund and budgeted reserve contribution
- The anticipated effects of appreciation of the reserves over time in accord with a return or yield on investment of your cash equivalent assets. (We did not consider the costs, if any, of Federal and State Taxes on income derived from interest and/or dividend income).
- The Funding Plan excludes necessary operating budget expenditures. It is our understanding that future operating budgets will provide for the ongoing normal maintenance of Reserve Components.

Updates to this Reserve Study will continue to monitor historical facts and trends concerning the external market conditions.



6. CREDENTIALS

HISTORY AND DEPTH OF SERVICE

Founded in 1991, Reserve Advisors is the leading provider of reserve studies, insurance appraisals, developer turnover transition studies, expert witness services, and other engineering consulting services. Clients include community associations, resort properties, hotels, clubs, non-profit organizations, apartment building owners, religious and educational institutions, and office/commercial building owners in 48 states, Canada and throughout the world.

The **architectural engineering consulting firm** was formed to take a leadership role in helping fiduciaries, boards, and property managers manage their property like a business with a long-range master plan known as a Reserve Study.

Reserve Advisors employs the **largest staff of Reserve Specialists** with bachelor's degrees in engineering dedicated to Reserve Study services. Our founders are also founders of Community Associations Institute's (CAI) Reserve Committee that developed national standards for reserve study providers. One of our founders is a Past President of the Association of Professional Reserve Analysts (APRA). Our vast experience with a variety of building types and ages, on-site examination and historical analyses are keys to determining accurate remaining useful life estimates of building components.

No Conflict of Interest - As consulting specialists, our **independent opinion** eliminates any real or perceived conflict of interest because we do not conduct or manage capital projects.

TOTAL STAFF INVOLVEMENT

Several staff members participate in each assignment. The responsible advisor involves the staff through a Team Review, exclusive to Reserve Advisors, and by utilizing the experience of other staff members, each of whom has served hundreds of clients. We conduct Team Reviews, an internal quality assurance review of each assignment, including: the inspection; building component costing; lifing; and technical report phases of the assignment. Due to our extensive experience with building components, we do not have a need to utilize subcontractors.

OUR GOAL

To help our clients fulfill their fiduciary responsibilities to maintain property in good condition.

VAST EXPERIENCE WITH A VARIETY OF BUILDINGS

Reserve Advisors has conducted reserve studies for a multitude of different communities and building types. We've analyzed thousands of buildings, from as small as a 3,500-square foot day care center to a 2,600,000-square foot 98-story highrise. We also routinely inspect buildings with various types of mechanical systems such as simple electric heat, to complex systems with air handlers, chillers, boilers, elevators, and life safety and security systems.

We're familiar with all types of building exteriors as well. Our well-versed staff regularly identifies optimal repair and replacement solutions for such building exterior surfaces such as adobe, brick, stone, concrete, stucco, EIFS, wood products, stained glass and aluminum siding, and window wall systems.

OLD TO NEW

Reserve Advisors' experience includes ornate and vintage buildings as well as modern structures. Our specialists are no strangers to older buildings. We're accustomed to addressing the unique challenges posed by buildings that date to the 1800's. We recognize and consider the methods of construction employed into our analysis. We recommend appropriate replacement programs that apply cost effective technologies while maintaining a building's character and appeal.

J.J. Barron
Responsible Advisor

CURRENT CLIENT SERVICES

J.J. Barron, a Mechanical Engineer, is an Advisor for Reserve Advisors. Mr. Barron is responsible for the inspection and analysis of the condition of clients' properties, and recommending engineering solutions to prolong the lives of the components. He also forecasts capital expenditures for the repair and/or replacement of the property components and prepares technical reports on assignments. He is responsible for conducting Life Cycle Cost Analyses and Capital Replacement Forecast services and the preparation of Reserve Study Reports for condominiums, townhomes and homeowner associations.



The following is a partial list of clients served by J.J. Barron demonstrating his breadth of experiential knowledge of community associations in construction and related buildings systems.

Sunset Lakes Condominium Association - Located in Lakeland, Florida, this condominium association contains 288 units in 12 three-story buildings. The Association maintains a pool and club house, building exteriors including roofs and painting, and asphalt pavement.

Jacksonville Golf & Country Property Owners Association - This homeowners association is located in Jacksonville, Florida. This community consist of 919 single family homes. Jacksonville Golf & Country maintains a dock area that consist of asphalt pavement, concrete sidewalks, and storm drains. The Association is also responsible for landscaping, irrigation, and gate entry systems.

Eagle Dunes Homeowners Association, Inc. - Located in Sorrento, Florida, this homeowners association contains 679 single family homes and 104 townhome units. Eagle Dunes maintains several ponds throughout the community. The association maintains playground equipment, tennis courts, gates and gate entry systems. The community also maintains various fencing and landscaping.

Tidewater Island Condominium Association, Inc. - This development comprises of 38 single family homes across 5 three- story buildings. This Community Association is located in Vero Beach, Florida. Asphalt shingle roofs, elevators, HVAC split systems, and parking garages. This community also maintains breezeways, balconies, and fire suppression systems.

The Seasons at Orchid Homeowners Association, Inc. - Located in Vero Beach, Florida, this Association is responsible for the common elements shared by 100 single family homes. In addition to roads and parking areas, the Association maintains a clubhouse and gatehouse with concrete tile roofs, a swimming pool, exercise equipment and perimeter walls.

Runaway Beach Club Condominium Association, Inc. - This homeowners association is located in Kissimmee, Florida, and is responsible for the common elements shared by 192 single family homes. The Association maintains a clubhouse with a basketball court, weight room, an office, golf carts, a pool and pool deck pavers.

PRIOR RELEVANT EXPERIENCE

Mr. Barron earned his Bachelor of Science degree in Mechanical Engineering from the University of Texas at Tyler. His relevant coursework includes thermodynamics, fluid mechanics, heat transfer, mechanical design, control systems, computer-aided engineering, building systems engineering, materials science, project management, energy management, structural analysis, and life cycle cost analysis.

EDUCATION

University of Texas at Tyler – B.S. Mechanical Engineering

Kevin Hayes
Regional Engineering Manager

CURRENT CLIENT SERVICES

Kevin Hayes is an Advisor for Reserve Advisors. Mr. Hayes is responsible for the inspection and analysis of the condition of clients' properties, and recommending engineering solutions to prolong the lives of the components. He also forecasts capital expenditures for the repair and/or replacement of the property components and prepares technical reports on assignments. He is responsible for conducting Life Cycle Cost Analyses and Capital Replacement Forecast services and the preparation of Reserve Study Reports for condominiums, townhomes and homeowner associations.



The following is a partial list of clients served by Kevin Hayes demonstrating his breadth of experiential knowledge of community associations in construction, remediation procedures and related buildings systems.

Silver Springs Farms Estates Association - Located in Banner Elk, North Carolina, Silver Springs Farms sits upon the foothills of the North Carolina Appalachian mountain range and produces some of the best views that North Carolina has to offer. Silver Springs Farms contains various scenic waterfalls, breathtaking landscapes, mountain-typical winding asphalt roads, and many large retaining walls.

1666 Coffman Condominium Association - Located in Falcon Heights, Minnesota, this distinctive building contains 93 units in a three-story structure. Building service elements include boilers, a chiller, a hydraulic elevator, and various pumps that supply water for building heating/cooling as well as fire suppression.

Robinwood Village Homeowners Association - This development contains a combination of 18 townhome style buildings in Gastonia, North Carolina. The Association maintains shared common elements including asphalt pavement streets, retaining walls and walking paths.

Oldenburg Homeowners Association - This development contains 128 single family homes in Waxhaw, North Carolina. The Association maintains shared common elements including asphalt pavement streets, walking paths, sport courts, clubhouse and pool.

Stowe Creek Homeowners Association - This development contains 396 single family homes in Charlotte, North Carolina. The Association maintains shared common elements including asphalt pavement streets, playground equipment, clubhouse and pool.

IronGate Farms Homeowners Association - This development contains 30 single family homes in Clover, South Carolina. The Association maintains shared common elements including asphalt pavement streets, walking paths, ponds, and perimeter fences.

PRIOR RELEVANT EXPERIENCE

Mr. Hayes attended North Carolina State University at Charlotte in Charlotte, North Carolina where he attained his Bachelor of Science degree in Electrical Engineering Technology. He then worked as a manufacturing engineer for Continental Automotive Systems where he maintained the electrical, mechanical, hydraulic, and pneumatic control systems of various production equipment. Mr. Hayes also developed PLC logic as well as vision system solutions to ensure a high standard of quality within the production processes of his responsibility. Mr. Hayes later managed a department of 5 engineers and over 20 technicians that were responsible for the entire final assembly of state-of-the-art automotive safety technology before joining Reserve Advisors as a Regional Engineering Manager of the Southeast Region.

EDUCATION

University of North Carolina at Charlotte - B.S. Electrical Engineering Technology

ALAN M. EBERT, P.E., PRA, RS
Director of Quality Assurance

CURRENT CLIENT SERVICES

Alan M. Ebert, a Professional Engineer, is the Director of Quality Assurance for Reserve Advisors. Mr. Ebert is responsible for the management, review and quality assurance of reserve studies. In this role, he assumes the responsibility of stringent report review analysis to assure report accuracy and the best solution for Reserve Advisors' clients.

Mr. Ebert has been involved with thousands of Reserve Study assignments. The following is a partial list of clients served by Alan Ebert demonstrating his breadth of experiential knowledge of community associations in construction and related buildings systems.



Brownsville Winter Haven Located in Brownsville, Texas, this unique homeowners association contains 525 units. The Association maintains three pools and pool houses, a community and management office, landscape and maintenance equipment, and nine irrigation canals with associated infrastructure.

Rosemont Condominiums This unique condominium is located in Alexandria, Virginia and dates to the 1940's. The two mid-rise buildings utilize decorative stone and brick masonry. The development features common interior spaces, multi-level wood balconies and common asphalt parking areas.

Stillwater Homeowners Association Located in Naperville, Illinois, Stillwater Homeowners Association maintains four tennis courts, an Olympic sized pool and an upscale ballroom with commercial-grade kitchen. The community also maintains three storm water retention ponds and a detention basin.

Birchfield Community Services Association This extensive Association comprises seven separate parcels which include 505 townhome and single family homes. This Community Services Association is located in Mt. Laurel, New Jersey. Three lakes, a pool, a clubhouse and management office, wood carports, aluminum siding, and asphalt shingle roofs are a few of the elements maintained by the Association.

Oakridge Manor Condominium Association Located in Londonderry, New Hampshire, this Association includes 104 units at 13 buildings. In addition to extensive roads and parking areas, the Association maintains a large septic system and significant concrete retaining walls.

Memorial Lofts Homeowners Association This upscale high rise is located in Houston, Texas. The 20 luxury units include large balconies and decorative interior hallways. The 10-story building utilizes a painted stucco facade and TPO roof, while an on-grade garage serves residents and guests.

PRIOR RELEVANT EXPERIENCE

Mr. Ebert earned his Bachelor of Science degree in Geological Engineering from the University of Wisconsin-Madison. His relevant course work includes foundations, retaining walls, and slope stability. Before joining Reserve Advisors, Mr. Ebert was an oilfield engineer and tested and evaluated hundreds of oil and gas wells throughout North America.

EDUCATION

University of Wisconsin-Madison - B.S. Geological Engineering

PROFESSIONAL AFFILIATIONS/DESIGNATIONS

Professional Engineering License – Wisconsin, North Carolina, Illinois, Colorado

Reserve Specialist (RS) - Community Associations Institute

Professional Reserve Analyst (PRA) - Association of Professional Reserve Analysts



RESOURCES

Reserve Advisors utilizes numerous resources of national and local data to conduct its Professional Services. A concise list of several of these resources follows:

Association of Construction Inspectors, (ACI) the largest professional organization for those involved in construction inspection and construction project management. ACI is also the leading association providing standards, guidelines, regulations, education, training, and professional recognition in a field that has quickly become important procedure for both residential and commercial construction, found on the web at www.iami.org.

American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc., (ASHRAE) the American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc., devoted to the arts and sciences of heating, ventilation, air conditioning and refrigeration; recognized as the foremost, authoritative, timely and responsive source of technical and educational information, standards and guidelines, found on the web at www.ashrae.org. Reserve Advisors actively participates in its local chapter and holds individual memberships.

Community Associations Institute, (CAI) America's leading advocate for responsible communities noted as the only national organization dedicated to fostering vibrant, responsive, competent community associations. Their mission is to assist community associations in promoting harmony, community, and responsible leadership.

Marshall & Swift / Boeckh, (MS/B) the worldwide provider of building cost data, co-sourcing solutions, and estimating technology for the property and casualty insurance industry found on the web at www.marshallswift.com.

R.S. Means CostWorks, North America's leading supplier of construction cost information. As a member of the Construction Market Data Group, Means provides accurate and up-to-date cost information that helps owners, developers, architects, engineers, contractors and others to carefully and precisely project and control the cost of both new building construction and renovation projects found on the web at www.rsmeans.com.

Reserve Advisors' library of numerous periodicals relating to reserve studies, condition analyses, chapter community associations, and historical costs from thousands of capital repair and replacement projects, and product literature from manufacturers of building products and building systems.

7. DEFINITIONS

Definitions are derived from the standards set forth by the Community Associations Institute (CAI) representing America's 305,000 condominium and homeowners associations and cooperatives, and the Association of Professional Reserve Analysts, setting the standards of care for reserve study practitioners.

Cash Flow Method - A method of calculating Reserve Contributions where contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different Reserve Funding Plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

Component Method - A method of developing a Reserve Funding Plan with the total contribution is based on the sum of the contributions for individual components.

Current Cost of Replacement - That amount required today derived from the quantity of a *Reserve Component* and its unit cost to replace or repair a Reserve Component using the most current technology and construction materials, duplicating the productive utility of the existing property at current *local* market prices for *materials*, *labor* and manufactured equipment, contractors' overhead, profit and fees, but without provisions for building permits, overtime, bonuses for labor or premiums for material and equipment. We include removal and disposal costs where applicable.

Fully Funded Balance - The Reserve balance that is in direct proportion to the fraction of life "used up" of the current Repair or Replacement cost similar to Total Accrued Depreciation.

Funding Goal (Threshold) - The stated purpose of this Reserve Study is to determine the adequate, not excessive, minimal threshold reserve balances.

Future Cost of Replacement - *Reserve Expenditure* derived from the inflated current cost of replacement or current cost of replacement as defined above, with consideration given to the effects of inflation on local market rates for materials, labor and equipment.

Long-Lived Property Component - Property component of Kingston Plantation responsibility not likely to require capital repair or replacement during the next 30 years with an unpredictable remaining Useful Life beyond the next 30 years.

Percent Funded - The ratio, at a particular point of time (typically the beginning of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage.

Remaining Useful Life - The estimated remaining functional or useful time in years of a *Reserve Component* based on its age, condition and maintenance.

Reserve Component - Property elements with: 1) Kingston Plantation responsibility; 2) limited Useful Life expectancies; 3) predictable Remaining Useful Life expectancies; and 4) a replacement cost above a minimum threshold.

Reserve Component Inventory - Line Items in *Reserve Expenditures* that identify a *Reserve Component*.

Reserve Contribution - An amount of money set aside or *Reserve Assessment* contributed to a *Reserve Fund* for future *Reserve Expenditures* to repair or replace *Reserve Components*.

Reserve Expenditure - Future Cost of Replacement of a Reserve Component.

Reserve Fund Status - The accumulated amount of reserves in dollars at a given point in time, i.e., at year end.

Reserve Funding Plan - The portion of the Reserve Study identifying the *Cash Flow Analysis* and containing the recommended Reserve Contributions and projected annual expenditures, interest earned and reserve balances.

Reserve Study - A budget planning tool that identifies the current status of the reserve fund and a stable and equitable Funding Plan to offset the anticipated future major common area expenditures.

Useful Life - The anticipated total time in years that a *Reserve Component* is expected to serve its intended function in its present application or installation.



8. PROFESSIONAL SERVICE CONDITIONS

Our Services - Reserve Advisors, LLC ("RA") performs its services as an independent contractor in accordance with our professional practice standards and its compensation is not contingent upon our conclusions. The purpose of our reserve study is to provide a budget planning tool that identifies the current status of the reserve fund, and an opinion recommending an annual funding plan, to create reserves for anticipated future replacement expenditures of the subject property. The purpose of our energy benchmarking services is to track, collect and summarize the subject property's energy consumption over time for your use in comparison with other buildings of similar size and establishing a performance baseline for your planning of long-term energy efficiency goals. The purpose of our Milestone Phase I is to evaluate the structural integrity of the building on the subject property and provide an inspection report summarizing our findings related to structural issues, or lack thereof.

In each case, our inspection and analysis of the subject property is limited to visual observations, is noninvasive and is not meant to nor does it include investigation into statutory, regulatory or code compliance. RA inspects sloped roofs from the ground and inspects flat roofs where safe access (stairs or ladder permanently attached to the structure) is available. Our energy benchmarking services with respect to the subject property is limited to collecting energy and utility data and summarizing such data in the form of an Energy Star Portfolio Manager Report or any other similar report, and hereby expressly excludes any recommendations with respect to the results of such energy benchmarking services or the accuracy of the energy information obtained from utility companies and other third-party sources with respect to the subject property. Our Milestone Phase I inspections are limited to a visual examination of habitable and uninhabitable areas of the building, including the primary structural members and systems. The inspection aims to determine the presence of substantial structural deterioration, and unsafe or dangerous conditions with the structure. The reserve report, Milestone Phase 1 report, and any energy benchmarking report (i.e., any Energy Star Portfolio Manager Report) (including any subsequent revisions thereto pursuant to the terms hereof, collectively, the "Report") are based upon a "snapshot in time" at the moment of inspection. RA may note visible physical defects in the Report. The inspection is made by employees generally familiar with real estate and building construction. Except to the extent readily apparent to RA, RA cannot and shall not opine on the structural integrity of or other physical defects in the property under any circumstances. Without limitation to the foregoing, RA cannot and shall not opine on, nor is RA responsible for, the property's conformity to specific governmental code requirements for fire, building, earthquake, occupancy or otherwise.

RA is not responsible for conditions that have changed between the time of inspection and the issuance of the Report. RA does not provide invasive testing on any mechanical systems that provide energy to the property, nor can RA opine on any system components that are not easily accessible during the inspection. RA does not investigate, nor assume any responsibility for any existence or impact of any hazardous materials, such as asbestos, urea-formaldehyde foam insulation, other chemicals, toxic wastes, environmental mold or other potentially hazardous materials or structural defects that are latent or hidden defects which may or may not be present on or within the property. RA does not make any soil analysis or geological study as part of its services, nor does RA investigate vapor, water, oil, gas, coal, or other subsurface mineral and use rights or such hidden conditions, and RA assumes no responsibility for any such conditions. The Report contains opinions of estimated replacement costs or deferred maintenance expenses and remaining useful lives, which are neither a guarantee of the actual costs or expenses of replacement or deferred maintenance nor a guarantee of remaining useful lives of any property element.

RA assumes, without independent verification, the accuracy of all data provided to it. Except to the extent resulting from RA's willful misconduct in connection with the performance of its obligations under this agreement, you agree to indemnify, defend, and hold RA and its affiliates, officers, managers, employees, agents, successors and assigns (each, an "RA Party") harmless from and against (and promptly reimburse each RA Party for) any and all losses, claims, actions, demands, judgments, orders, damages, expenses or liabilities, including, without limitation, reasonable attorneys' fees, asserted against or to which any RA Party may become subject in connection with this engagement, including, without limitation, as a result of any false, misleading or incomplete information which RA relied upon that was supplied by you or others under your direction, or which may result from any improper use or reliance on the Report by you or third parties under your control or direction or to whom you provided the Report. NOTWITHSTANDING ANY OTHER PROVISION HEREIN TO THE CONTRARY, THE AGGREGATE LIABILITY (IF ANY) OF RA WITH RESPECT TO THIS AGREEMENT AND RA'S OBLIGATIONS HEREUNDER IS LIMITED TO THE AMOUNT OF THE FEES ACTUALLY RECEIVED BY RA FROM YOU FOR THE SERVICES AND REPORT PERFORMED BY RA UNDER THIS AGREEMENT, WHETHER ARISING IN CONTRACT, TORT (INCLUDING NEGLIGENCE), STRICT LIABILITY OR OTHERWISE. YOUR REMEDIES SET FORTH HEREIN ARE EXCLUSIVE AND ARE YOUR SOLE REMEDIES FOR ANY FAILURE OF RA TO COMPLY WITH ITS OBLIGATIONS HEREUNDER OR OTHERWISE. RA SHALL NOT BE LIABLE FOR ANY SPECIAL, INDIRECT, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES OF ANY KIND, INCLUDING, BUT NOT LIMITED TO, ANY LOST PROFITS AND LOST SAVINGS, LOSS OF USE OR INTERRUPTION OF BUSINESS, HOWEVER CAUSED, WHETHER ARISING IN CONTRACT, TORT (INCLUDING NEGLIGENCE), BREACH OF WARRANTY, STRICT LIABILITY OR OTHERWISE, EVEN IF RA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. IN NO EVENT WILL RA BE LIABLE FOR THE COST OF PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES. RA DISCLAIMS ALL REPRESENTATIONS AND WARRANTIES WHATSOEVER, EXPRESS OR IMPLIED OR OF ANY NATURE, WITH REGARD TO THE SERVICES AND THE REPORT, INCLUDING, WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.



Report - RA will complete the services in accordance with the Proposal. The Report represents a valid opinion of RA's findings and recommendations with respect to the reserve study or Milestone Phase I, as applicable, and is deemed complete. RA will consider any additional information made available to RA within 6 months of issuing the Report and issue a revised Report based on such additional information if a timely request for a revised Report is made by you. RA retains the right to withhold a revised Report if payment for services was not tendered in a timely manner. All information received by RA and all files, work papers or documents developed by RA during the course of the engagement shall remain the property of RA and may be used for whatever purpose it sees fit. RA reserves the right to, and you acknowledge and agree that RA may, use any data provided by you in connection with the services, or gathered as a result of providing such services, including in connection with creating and issuing any Report, in a de-identified and aggregated form for RA's business purposes.

Your Obligations - You agree to provide us access to the subject property for an inspection. You agree to provide RA all available, historical and budgetary information, the governing documents, and other information that we request and deem necessary to complete the Report. Additionally, you agree to provide historical replacement schedules, utility bills and historical energy usage files that RA requests and deems necessary to complete the energy benchmarking services, and you agree to provide any utility release(s) reasonably requested by RA permitting RA to obtain any such data and/or information from any utility representative or other third party. You agree to pay actual attorneys' fees and any other costs incurred to collect on any unpaid balance for RA's services.

Use of Our Report and Your Name - Use of the Report is limited to only the purpose stated herein. You acknowledge that RA is the exclusive owner of all intellectual property rights in and relating to the Report. You hereby acknowledge that any use or reliance by you on the Report for any unauthorized purpose is at your own risk and that you will be liable for the consequences of any unauthorized use or distribution of the Report. Use or possession of the Report by any unauthorized third party is prohibited. The Report in whole or in part ***is not and cannot be used as a design specification for design engineering purposes or as an appraisal.*** You may show the Report in its entirety to the following third parties: members of your organization (including your directors, officers, tenants and prospective purchasers), your accountants, attorneys, financial institutions and property managers who need to review the information contained herein, and any other third party who has a right to inspect the Report under applicable law including, but not limited to, any government entity or agency, or any utility companies. Without the written consent of RA, you shall not disclose the Report to any other third party. By engaging our services, you agree that the Report contains intellectual property developed (and owned solely) by RA and agree that you will not reproduce or distribute the Report ***to any party that conducts reserve studies without the written consent of RA.***

RA will include (and you hereby agree that RA may include) your name in our client lists. RA reserves the right to use (and you hereby agree that RA may use) property information to obtain estimates of replacement costs, useful life of property elements or otherwise as RA, in its sole discretion, deems appropriate.

Payment Terms, Due Dates and Interest Charges - The retainer payment for any reserve study, Milestone Phase I inspection, and/or combined services is due upon execution of this agreement and prior to the inspection by RA, and any balance is due net 30 days from the Report shipment date. If only energy benchmarking services are performed by RA, then the retainer payment is due upon execution of this agreement and any balance is due net 30 days from the Report shipment date. In any case, any balance remaining 30 days after delivery of the Report shall accrue an interest charge of 1.5% per month. Unless this agreement is earlier terminated by RA in the event you breach or otherwise fail to comply with your obligations under this agreement, RA's obligations under this agreement shall commence on the date you execute and deliver this agreement and terminate on the date that is 6 months from the date of delivery of the Report by RA. Notwithstanding anything herein to the contrary, each provision that by its context and nature should survive the expiration or early termination of this agreement shall so survive, including, without limitation, any provisions with respect to payment, intellectual property rights, limitations of liability and governing law. We reserve the right to limit or decline refunds in our sole discretion. Refunds vary based on the applicable facts and circumstances.

Miscellaneous – Neither party shall be liable for any failures or delays in performance due to fire, flood, strike or other labor difficulty, act of God, act of any governmental authority, riot, embargo, fuel or energy shortage, pandemic, wrecks or delays in transportation, or due to any other cause beyond such party's reasonable control; provided, however, that you shall not be relieved from your obligations to make any payment(s) to RA as and when due hereunder. In the event of a delay in performance due to any such cause, the time for completion or date of delivery will be extended by a period of time reasonably necessary to overcome the effect of such delay. You may not assign or otherwise transfer this agreement, in whole or in part, without the prior written consent of RA. RA may freely assign or otherwise transfer this agreement, in whole or in part, without your prior consent. This agreement shall be governed by the laws of the State of Wisconsin without regard to any principles of conflicts of law that would apply the laws of another jurisdiction. Any dispute with respect to this agreement shall be exclusively venued in Milwaukee County Circuit Court or in the United States District Court for the Eastern District of Wisconsin. Each party hereto agrees and hereby waives the right to a trial by jury in any action, proceeding or claim brought by or on behalf of the parties hereto with respect to any matter related to this agreement.